

Daily Observation Report

Date of Report: Sept. 13, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1

REPORT #: 101

Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 45*	Snow	Windy	
High Temperature: 68*	X Sunny	Clear	
	Clear	Snow	
CONDITIONS	Other	X Partly Cloudy	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	Kit	
Flooring Roofers	Caulking	Dakota 1	
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew 25	
Landscapers Tile Setters	Electricians		
Carpenter Others:			
Totals:	26		
Observations – 1) E1: Units 8 & 11 deck fill dirt installation. 2) E2: Units 20 - 23 J channel and soffit installation continued. Units 20, 21 & 23 deck door installation. 3) E3: Units 24 - 27 deck fill dirt installation. 4) E4: Units 28 & 31 side lap siding installed. Units 28 & 29 board and batten installation. Units 30 & 31 J channel installation. TESTS/INSPECTIONS — UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —			



Daily Observation Report - cont.



Building E1 Unit 11 Deck Back Fill Installed



Building E3 Unit 24 Deck Back Fill Installed



Building E2 Units 20 & 21 Front Soffit Installed



Building E2 Units 21 & 22 Deck Door Threshold Pan Flashing Installed



Daily Observation Report – cont.



Building E4 Units 28 & 29 Board and Batten Siding Installed



Building E4 Unit 28 Side Lap Siding Installed



Daily Observation Report

Date of Report: Sept. 14, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1

REPORT #: 102

Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 39*	Snow	Windy	
High Temperature: 75*	X Sunny	Clear	
	Clear	Snow	
CONDITIONS	Other	X Partly Cloudy	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	Kit	
Flooring Roofers	Caulking	Dakota 1	
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew 25	
Landscapers Tile Setters	Electricians		
Carpenter Others:			
Totals:	26		
Observations – 1) E2: Units 20 - 23 foam board, window/door trim, J channel, corrugated and lap siding installation continued. 2) E3: Unit 27 deck framing began. 3) E4: Units 28 & 31 side lap siding installation continued. Units 30 & 31 front board and batten installation. TESTS/INSPECTIONS – UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –			



Daily Observation Report - cont.



Building E2 Units 20 & 21 Back Foam Board and J Channel Installed



Building E2 Units 21 & 22 Back Foam Board and J Channel Installed



Building E2 Units 21 & 22 Front Lap Siding and J Channel Installed



Building E2 Units 20 & 21 Front Window Trim and J Channel Installed



Building E3 Unit 27 Deck Framing Began



Building E4 Unit 28 Side Lap Siding Installed



Daily Observation Report

Date of Report: Sept. 15, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1	Report #: 103

Address: Running Bear Road		
WEATHER		
TEMPERATURE	A.M	P.M
Low Temperature: 45*	Snow	Windy
High Temperature: 84*	X Sunny	Clear
	Clear	Snow
CONDITIONS	Other	X Partly Cloudy
CREW ON SITE		
Plasterers Finish Carpenters	Plumbers	Kit
Flooring Roofers	Caulking	Dakota 1
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew 25
Landscapers Tile Setters	Electricians	
Carpenter Others:		
Totals:	26	
Observations – 1) E2: Units 20 - 23 foam board, window/door trim, J channel, corrugated and lap siding installation continued. 2) E3: Unit 27 deck framing completed. 3) E4: Units 28 & 31 back lap siding installation continued. Units 28 side board and batten installation. TESTS/INSPECTIONS – UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –		



Daily Observation Report - cont.



Building E2 Unit 23 Deck Door Installation



Building E2 Units 21 & 22 Deck Door Trim and J Channel Installation



Building E3 Unit 27 Deck Framing Installed



Building E4 Unit 28 Side Board and Batten Installation



Montana Construction Management PO Box 1508, Great Falls, MT 59401 (406) 799-9434

Daily Observation Report

Date of Report: Sept. 16, 2021 Prepared By: Jim Goveia

montanaconstmgmt@gmail.com

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1			R EPORT #: 104
Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 50*	Snow	Windy	
High Temperature: 63*	X Sunny	Clear	
	Clear	Snow	
CONDITIONS	Other	X Partly	Cloudy
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	Kit	
Flooring Roofers	Caulking	Dakota	1
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew	26
Landscapers Tile Setters	Electricians		
Carpenter Others:			
Totals:	27		
Observations – 1) E2: Units 20 - 23 corrugated and lap siding installation continued. 2) E3: Unit 26 deck framing began. 3) E4: Units 28 & 31 back lap siding installation continued. Units 28 side board and batten installation. TESTS/INSPECTIONS – UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –			



Daily Observation Report – cont.



Building E2 Unit 23 Back Corrugated Siding Installed



Building E2 Units 20 & 21 Back Lap Siding Installed



Building E3 Unit 26 Deck Framing Began



Building E4 Unit 31 Side Board and Batten Siding Installed



Daily Observation Report

Date of Report: Sept. 17, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1

REPORT #: 105

Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 39*	Snow	Windy	
High Temperature: 81*	X Sunny	Clear	
	Clear	Snow	
CONDITIONS	Other	X Sunny	
CREW ON SITE			
Plasterers Finish Carpenters Plu	mbers	Kit	
Flooring Roofers Ca	ılking	Dakota 1	
Ceiling Sheet rockers/Tapers Co	ncrete Finishers	Siding Crew 26	
Landscapers Tile Setters Ele	ctricians		
Carpenter Others:			
Totals: 27			
Observations – 1) E1: Units 8 - 11 back lap & board and batten siding installation continued. 2) E2: Units 20 - 23 back and sides lap siding installation continued. 3) E3: Unit 25 deck framing began. 4) E4: Units 27 - 31 back lap siding installation continued. TESTS/INSPECTIONS – Structural engineer inspection of units 26 & 27 decks and no deficiencies were found. UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –			



Daily Observation Report – cont.



Building E1 Unit 9 Back Lap & Board and Batten Siding Installed



Building E2 Unit 23 Back & Side Lap Siding Installed



Building E3 Unit 26 Deck Framing Completed



Building E4 Units 28 & 29 Back Lap Siding Installed