

Daily Observation Report

Date of Report: Oct 18, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1			
Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 35*	Snow	Windy	
High Temperature: 63*	X Cloudy	Clear	
	Clear	Snow	
CONDITIONS	Other	X Sunny	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	Kit	
Flooring Roofers	Caulking	Dakota 1	
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew 26	
Landscapers Tile Setters	Electricians		
Carpenter Others:			
Totals:	27		
Observations – 1) E2: Units 22 & 23 decking completed. 2) E7: Units 49 - 52 front siding installation continued. Units 50 - 52 back board and batten siding installation continued. 3) F2: Units 18 & 19 fascia, soffit, base flashing & wainscot flashing continued. TESTS/INSPECTIONS – UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –			





Building E2 Unit 23 Deck Complete



Building E2 Unit 22 Deck Complete



Building E7 Units 51 & 52 Back Board and Batten Installation



Building E7 Unit 52 Side Siding Installation



Building F2 Unit 19 Side Base & Wainscot Flash Installation



Building F2 Unit 18 Side Fascia & Soffit Installation



PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1

Daily Observation Report

REPORT #: 127

Date of Report: Oct 19, 2021 Prepared By: Jim Goveia

Address: Running Bear Road			
WEATHER			
Temperature	A.M	P.M	
Low Temperature: 36*	Snow	Windy	
High Temperature: 54*	X Cloudy	Clear	
	Clear	Snow	
CONDITIONS	Other	X Sunny	


CREW ON SITE Plasterers Finish Carpenters Plumbers Kit **Flooring** Roofers Caulking Dakota Sheet rockers/Tapers Ceiling **Concrete Finishers Siding Crew** 26 Landscapers **Tile Setters** Electricians Carpenter Others: TOTALS: 27

Observations – 1) E1: Units 8 - 10 deck area grading to lower grade below glulam. Units 8 - 11 vents installation began 2) E3: Units 24 - 27 vents installed 3) E4: Unit 28 drywall repair at entry began. 4) E7: Units 49 - 52 front siding installation continued. Units 49 & 50 back fascia & soffit installation continued. 5) F2: Units 18 & 19 fascia, soffit, base flashing & wainscot flashing continued and back sheathing replaced over repaired structural framing. Unit 19 kitchen window installed.

TESTS/INSPECTIONS —

UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY -





Building E1 Unit 8 Deck Area Grading



Building E7 Unit 50 Side Lap Siding & Diverter Installation



Building E3 Unit 24 Back Vents Installed



Building F2 Unit 19 Kitchen Window, Wainscot Flashing & Foam Insulation Installation



Daily Observation Report

Date of Report: Oct 20, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTER	UOD LIDODADES DUASE 1		Report #: 128
Address: Running Bear Road	HOR OPGRADES PHASE I		REPORT #. 120
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 27*	Snow	Windy	
High Temperature: 55*	X Cloudy	Clear	
	Clear	Snow	
CONDITIONS	Other	X Cloudy	
Crew On Site			
Plasterers Finish Carpenters	Plumbers	Kit	
Flooring Roofers	Caulking	Dakota	1
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew	20
Landscapers Tile Setters	Electricians	<u> </u>	
Carpenter Others:			
Totals:	21		
Observations – 1) E1: Units 8 - 10 deck area grading continued. 2) E2: Units 20 - 23 vents installed 3) E3: Units 24 - 27 addresses applied. 4) E4: Units 28 - 31 vents installed. Unit 28 drywall repair at entry progressing. 5) E7: Units 49 - 52 front siding installation continued. Units 51 & 52 front doors installed. 6) F2: Units 18 & 19 fascia, soffit, base flashing & belly band flashing continued and back sheathing installed over deck and railing blocking. Unit 18 kitchen window installed. TESTS/INSPECTIONS – UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –			





Building E1 Unit 8 Deck Area Grading



Building E4 Unit 28 Entry Interior Drywall Repair Progressing



Building E3 Address Numbers Applied



Building E7 Unit 51 Front Door Installation





Building F2 Unit 18 Back Deck Sheathing Installation



Building F2 Units 18 & 19 Front Tyvek, Belly Band, Base Flashing & Foam Board Install



Daily Observation Report

Date of Report: Oct 21, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTER	IOR UPGRADES PHASE 1		REPORT # : 129
Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 37*	Snow	Windy	
High Temperature: 64*	X Cloudy	Clear	
	Clear	Snow	
CONDITIONS	Other	X Sunny	
Crew On Site			
Plasterers Finish Carpenters	Plumbers	_ Kit	
Flooring Roofers	Caulking	_ Dakota	1
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew	18
Landscapers Tile Setters	Electricians	_	
Carpenter Others:			
Totals:	19		
Observations – 1) E1: Units 8 - 10 deck area grading continued. Units 8 - 10 Addresses applied. 2) E2: Units 20 - 23 addresses and lights installed. 3) E3: Units 24 - 27 addresses applied. 4) E4: Units 28 - 31 addresses and lights installed. Unit 28 drywall repair at entry progressing. 5) E7: Units 49 - 52 front siding installation continued. Units 51 & 52 front doors installed. 6) F2: Units 18 & 19 front lap siding continued and back sheathing installed over deck and railing blocking. TESTS/INSPECTIONS — UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —			





Building E1 Unit 8 Deck Grading Completed



Building E1 Units 8 & 9 Addresses Applied



Building E4 Units 28 & 29 Addresses Applied



Building E7 Units 49 & 50 Back Window <u>Trim Installation</u>



Building F2 Unit 19 Deck Blocking Sheathing Installation



Daily Observation Report

Date of Report: Oct 22, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & E	EXTERIOR UPGRADES P	HASE 1		REPORT # : 130
Address: Running Bear Road				
WEATHER				
TEMPERATURE	A.M		P.M	
Low Temperature: 34*		Snow	Wind	ly
High Temperature: 70*	Х	Partly Cloudy	Clea	r
		Clear	Snov	v
Conditions		Other	X Suni	ηγ
Crew On Site				
Plasterers Finish Carpenters	Plumbers		Kit	
Flooring Roofers	Caulking		Dakota	1
Ceiling Sheet rockers/Tapers	Concrete Finis	shers	Siding Crew	18
Landscapers Tile Setters	Electricians			
Carpenter Others:				
Тотл	TALS: 19			
Observations – 1) E1: Unit 8 decking installation continued. 2) E3: Units 24 - 27 touch up paint and caulking installation continued. 3) E7: Units 51 - 52 front siding installation continued. Units 49 & 50 board and batten siding installation continued. 4) F1: Units 16 & 17 addresses and lights installed. 5) F2: Units 18 & 19 front tyvek installation continued. TESTS/INSPECTIONS — UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —				





Building E1 Unit 8 Decking Installation



Building E3 Unit 25 Front Caulking Applied



Building E7 Units 51 & 52 Front Corrugated
Siding Installation



Building E7 Units 49 & 50 Back Board and Batten Siding Installation



Building F1 Units 16 & 17 Addresses and <u>Lighting Installation</u>



Building F2 Units 18 & 19 Tyvek Installation