

Montana Construction Management PO Box 1508, Great Falls, MT 59401 (406) 799-9434

100) 799-9434

#### **Daily Observation Report**

Date of Report: Nov 8, 2021 Prepared By: Jim Goveia

montanaconstmgmt@gmail.com			
PROJECT: BIG HORN CONDO SIDING REPLACEMENT &	EXTERIOR UPGRADES PHASE 1	Re	PORT #: 141
Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 18*	Snow	Windy	
High Temperature: 45*	X Sunny	Clear	
	Clear	Snow	
CONDITIONS	Other	X Sunny	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	Kit	1
Flooring Roofers	Caulking	Dakota	1
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew	6
Landscapers Tile Setters	Electricians	Interior Trim Carpe	nter 1
Carpenter Others:			
To	TALS: 9		
Observations – 1) E3: Unit 8 Interior trim in		og posts installed <b>3)</b> F	2: Units 18
& 19 Back deck ledger and flashing installe	α.		
TESTS/INSPECTIONS —			
Unresolved Issues/Factors Contributing to	O DELAY -		
	1		
	1		



PROGRESS OF WORK (PHOTOS)



Building E1 Unit 8 Living Room Interior Trim Installed



Building E1 Unit 8 Deck Door Interior Trim Installed



Building F1 Unit 16 Deck Log Posts Installed



Building F2 Units 18 & 19 Deck Ledgers Installed

Commented [TS3]:

Commented [TS4R3]:



Montana Construction Management PO Box 1508, Great Falls, MT 59401 (406) 799-9434

**Daily Observation Report** Date of Report: Nov 9, 2021

Prepared By: Jim Goveia

(110)			
montanaconstmgmt@gmail.com			
PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXT	rerior Upgrades Phase 1	ı	REPORT #: 142
Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 25*	_	_	
	Snow	∐ Windy	
High Temperature: 35*	X Snow	Clear	
	Clear	Snow	
CONDITIONS	Other	X Snow	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	Kit	
Flooring Roofers	Caulking	Dakota	1
Ceiling Sheet rockers/Tapers		Siding Crew	7
Landscapers Tile Setters	Electricians	Interior Trim Carp	penter
Carpenter Others:			
Totals	s: 8		
Observations – 1) F1: Unit 17 Deck log posts	installed <b>2)</b> F2: Units 18 & 19	Back wainscot flashi	ing and front
doors installed. Unit 19 Deck post knife plate:			
TESTS/INSPECTIONS —			
UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO D	JELAY —		
	<u> </u>		
	1		





**Building F1 Unit 17 Deck Posts Installed** 



Building F2 Unit 19 Back Wainscot Flashing Installed



**Building F2 Unit 19 Front Door Installed** 



**Building F2 Unit 18 Front Door Installed** 



Montana Construction Management PO Box 1508, Great Falls, MT 59401 (406) 799-9434

montanaconstmgmt@gmail.com

#### **Daily Observation Report**

Date of Report: Nov 10, 2021 Prepared By: Jim Goveia

Address: Running Bear Road				
WEATHER				
TEMPERATURE	A.M	P.M		
Low Temperature: 17*	Snow	☐ Windy		
High Temperature: 42*	X Partly Clo	udy Clear		
	Clear	Snow		
CONDITIONS	Other	X Snow		
Crew On Site				
Plasterers Finish Carpenters	_ Plumbers _	Kit	1	
Flooring Roofers	Caulking	Dakota	1	
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew	9	
Landscapers Tile Setters	Electricians	Interior Trim Carp	enter 1	
Carpenter Others:		Satellite Dish Insta		
TOTALS	:· 13	Satellite Dish Hista	···-·· -	
TOTAL	10			
<b>Dbservations – 1)</b> E3 & E4 Units 26 and 30 Sa	tellite installed <b>2)</b> F1: Unit	t 16 Deck log posts cut to	o height.	
F2: Units 18 & 19 Back lap siding and deck	knife plates installation co	ontinued.		
FESTS/INSPECTIONS —				
Happen upp legues /Factors Contractions to	FLAV			
Unresolved Issues/Factors Contributing to D	ELAY —			
				Commented [TS2R1





**Building F2 Unit 19 Back Lap Siding Install** 



**Building F2 Unit 18 Deck Knife Plates Install** 



**Building F2 Unit 18 Back Lap Siding Install** 



**Building F2 Unit 19 Deck Knife Plates Install** 



Montana Construction Management PO Box 1508, Great Falls, MT 59401 (406) 799-9434 montanaconstmgmt@gmail.com

## **Daily Observation Report**

Date of Report: Nov 11, 2021 Prepared By: Jim Goveia

**PROJECT:** BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1

**R**EPORT #: 144

ADDDECC:	DUNINUNG	READ	POAD	

ADDRESS. RUNNING BEAR ROAD					
WEATHER					
TEMPERATURE	A.M	P.M			
Low Temperature: 18*	Rain	Windy			
High Temperature: 24*	X Snow	Clear			
	Clear	Rain			
Conditions	Other	X Snow			
Crew On Site					
Plasterers Finish Carpenters	Plumbers	_ Kit 1			
Flooring Roofers	Caulking	_ Dakota 1			
Ceiling Sheet rockers/Tapers	Concrete Finishers	_ Siding Crew 3			
Landscapers Tile Setters	Electricians	_ Interior Trim Carpenter 1			
Carpenter Others:		Satellite Dish Installer 2			
Totals:	8				
Observations – 1) F1: Units 16 & 17 Deck framing continued. 2) F2: Units 18 & 19 Back lap siding installation continued.  Satellite Installations  Unit 31 ran rg6 to DirecTV receiver.  Unit 28 installed masts and ran rg6 to crawlspace.  Unit 29 installed masts and ran rg6 to crawlspace.  Unit 23 installed mast and ran rg6 to crawlspace.  Unit 22 installed mount.  TESTS/INSPECTIONS —  UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —					





Building F1 Units 18 & 19 Deck Framing
Installation Continued



Building F1 Units 18 & 19 Deck Framing Installation Continued



Building F1 Unit 18 Deck Framing Installation Continued



Building E Units 22 & 23 Satellite Mounts Installation Continued





Building E4 Units 28 & 29 Satellite Mounts Installation Continued



Montana Construction Management PO Box 1508, Great Falls, MT 59401 (406) 799-9434 montanaconstmgmt@gmail.com

# **Daily Observation Report**

Date of Report: Nov 12, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1

REPORT #: 145

Address: Running Bear Road					
WEATHER					
TEMPERATURE	A.M	P.M			
Low Temperature: 24*	Rain	Windy			
High Temperature: 37*	X Mostly Cloudy	Clear			
	Clear	Snow			
CONDITIONS	Other	X Rain			
CREW ON SITE					
Plasterers Finish Carpenters	Plumbers I	Kit 1			
Flooring Roofers	Caulking	Dakota 1			
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew 9			
Landscapers Tile Setters	Electricians	Interior Trim Carpenter			
Carpenter Others:		Satellite Dish Installer			
TOTALS:	11				
Observations – 1) F1: Units 16 & 17 Deck framing continued. 2) F2: Units 18 & 19 Back lap siding & front corrugated siding installation continued.  Tests/Inspections –  Unresolved Issues/Factors Contributing to Delay –					





Building F1 Units 18 & 19 Deck Framing Installation Continued



Building F1 Unit 19 Deck Framing Installation Continued



Building F2 Units 18 & 19 Back Lap Siding Installation Continued



Building F2 Units 19 Front Corrugated Siding Installation Continued