

#### **Daily Observation Report**


Date of Report: Nov 15, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1

REPORT #: 146

Address: Running Bear Road			
WEATHER			
Temperature	A.M	P.M	
Low Temperature: 36*	Rain	Windy	
High Temperature: 48*	X Partly Cloudy	Clear	
	Clear	Snow	
CONDITIONS	Other	X Mostly Cloudy	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	Kit 1	
Flooring Roofers	Caulking	Dakota 1	
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew 7	
Landscapers Tile Setters	Electricians	Interior Trim Carpenter	
Carpenter Others:		Satellite Dish Installer	
Totals:	9		
Observations – 1) E1: Unit 10 Installed storm door. 2) E7: Units 49 - 51 Deck knife plates installation began. 3) F1: Unit 17 Deck framing continued. 4) F2: Units 18 & 19 Back corrugated siding installation continued.  TESTS/INSPECTIONS –  UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –			





**Building E1 Unit 10 Storm Door Installed** 



**Building F1 Unit 16 Decking Installed** 



Building E7 Units 49 - 51 Deck Knife Plates Installed



**Building F1 Unit 17 Deck Framing Continued** 





Building F2 Units 18 & 19 Back Corrugated
Siding Installed



Building F2 Units 18 & 19 Front Corrugated Siding Installed



## **Daily Observation Report**

Date of Report: Nov 16, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1	REPORT #: 147

Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 9*	Rain	Windy	
High Temperature: 23*	X Windy	Clear	
	Clear	Snow	
CONDITIONS	Other	X Windy	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	Kit	1
Flooring Roofers	Caulking	Dakota	1
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew	11
Landscapers Tile Setters	Electricians	Interior Trim Carpenter	-
Carpenter Others:			
Totals:	13		
Observations – 1) E7: Units 49 - 51 Deck knife plates installation continue. Deck log post preparation began. 2) F1: Unit 17 Decking began. 3) F2: Units 18 & 19 Back corrugated siding installation continued.  TESTS/INSPECTIONS –  UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –			

1





Building E7 Units 49 -51 Deck Knife Plates Installed



Building E7 Units 49 -51 Deck Posts Prepared for Installation



**Building F1 Unit 17 Decking Installation** 



Building F2 Units 18 & 19 Back Corrugated Siding Installed



installed and Unit 18 deck log posts installed.

UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY -

TESTS/INSPECTIONS -

#### **Daily Observation Report**

Date of Report: Nov 17, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REI	PLACEMENT & EXTERIOR	UPGRADES PH	HASE 1	ı	REPORT #: 148
Address: Running Bear Road					
WEATHER					
TEMPERATURE		A.M		P.M	
Low Temperature: 9*			Rain	Windy	
High Temperature: 20*		Х	Partly Cloudy	Clear	
			Clear	Snow	
CONDITIONS			Other	X Partly Cl	oudy
CREW ON SITE					
Plasterers Finish Carpe	nters P	lumbers		_ Kit	1
Flooring Roofers	C	aulking		Dakota	1
Ceiling Sheet rocker	s/Tapers C	oncrete Finis	shers	_ Siding Crew	10
Landscapers Tile Setters	E	ectricians		Satellite Dish Inst	aller 2
Carpenter Others:					
	Totals: 1	4			
Observations – 1) E1: Unit 11 St		d. <b>2)</b> E2: Un	its 20 - 23 Dish	es installed and wi	red. <b>3)</b> E4:

1

Unit 29 Storm door installed. 4) E7: Units 49 - 51 Deck knife plates installation continue. Deck log post installation continued. 5) F1: Unit 17 Deck fascia installed. 6) F2: Units 18 & 19 Back corrugated siding





**Building E1 Unit 11 Storm Door Installed** 



Building E7 Units 49 -51 Deck Posts Installation



**Building E4 Unit 29 Storm Door Installed** 



**Building F1 Unit 17 Deck Fascia Installed** 





Building F2 Units 18 & 19 Deck Posts Installed, Back Wainscot Siding Installed



UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY -

#### **Daily Observation Report**

Date of Report: Nov 18, 2021 Prepared By: Jim Goveia

**PROJECT:** BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1 **REPORT #: 149 ADDRESS: RUNNING BEAR ROAD W**EATHER **TEMPERATURE** P.M A.M Windy Low Temperature: 25\* Rain High Temperature: 30\* Partly Cloudy Clear Clear Snow **CONDITIONS** Other X Mostly Cloudy **CREW ON SITE** Plasterers **Finish Carpenters Plumbers** Kit 1 **Flooring** Roofers Caulking Dakota 1 Ceiling Sheet rockers/Tapers **Concrete Finishers Siding Crew** 10 2 Landscapers Tile Setters Electricians Satellite Dish Installer Carpenter Others: TOTALS: 14 Observations – 1) E2: Units 22 Storm door installed. 2) E4: Unit 29 Starlink dish installed and wired. 3) E7: Units 49 - 51 Deck knife plates installation continue. Deck log post installation continued. Units 49 & 51 Lap siding installation continued. 4) F1: Unit 16 Satellite dish installed and wired, unit 17 mount installed and wired. Unit 16 Storm door installed. 5) F2: Unit 18 deck log posts cut to length and ledger board lag bolts installed. TESTS/INSPECTIONS —





**Building E2 Unit 22 Storm Door Installed** 



**Building E7 Unit 51 Deck Knife Plates Installed** 



Building E7 Units 49 Deck Log Post Installation



Building E7 Units 49 & 50 Back Lap Siding Installation







Building F1 Units 16 Satellite Dish, Wire and Storm Door Installation

Building F2 Unit 18 Deck Logs & Ledger Bolts Installed



#### **Daily Observation Report**

Date of Report: Nov 19, 2021 Prepared By: Jim Goveia

**PROJECT:** BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1 **REPORT #**: 150

Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 26*	Rain	Windy	
High Temperature: 32*	X Snow	Clear	
	Clear	Rain	
CONDITIONS	Other	X Snow	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	Kit 1	
Flooring Roofers	Caulking	Dakota 1	
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew	
Landscapers Tile Setters	Electricians	Satellite Dish Installer	
Carpenter Others:			
Totals:	2		
Observations —  Tests/Inspections —  Unresolved Issues/Factors Contributing to Delay — No siding, deck or interior trim workers were present			
today. The 9 siding workers that were staying in Units 21 & 31 removed all their belongings and their vehicles were gone. MCM will coordinate with L&A regarding remaining work to be completed.			