

## **Daily Observation Report**

Date of Report: Nov 1, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIO	OR UPGRADES PHASE 1		<b>REPORT #</b> : 136
Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 25*	Snow	Windy	
High Temperature: 39*	X Foggy	Clear	
	Clear	Snow	
CONDITIONS	Other	X Partly	Cloudy
CREW ON SITE			
Plasterers Finish Carpenters F	Plumbers	Kit	
Flooring Roofers (	Caulking	Dakota	1
Ceiling Sheet rockers/Tapers (	Concrete Finishers	Siding Crew	13
Landscapers Tile Setters E	Electricians _	,	
Carpenter Others:			
Totals:	14		
Observations – 1) E7: Unit 52 deck door installation began, threshold mold and high moisture was detected. Units 49 & 50 back lap siding installation continued. 2) F1: Units 16 & 17 Deck materials were staged. 3) F2: Units 18 Side board and batten siding installation continued. Units 18 & 19 Back window trim and foam board installation continued. Unit 18 back upper window installed.  TESTS/INSPECTIONS –  UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –			






**Building E7 Unit 52 Deck Door Installation** 



Building E7 Unit 52 Deck Door Threshold Damage



Building E7 Unit 52 Deck Door Threshold Damage



**Building E7 Unit 49 Back Lap Siding Install** 





Building F2 Unit 18 Side Board and Batten Installation



**Building F2 Unit 18 Back Upper Window Install** 



#### **Daily Observation Report**

Date of Report: Nov 2, 2021 Prepared By: Jim Goveia

**PROJECT:** BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1

**Report** #: 137

**ADDRESS:** RUNNING BEAR ROAD

WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 21*	Snow	Windy	
High Temperature: 43*	X Cloudy	Clear	
	Clear	Snow	
CONDITIONS	Other	X Cloudy	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers Ki	t	
Flooring Roofers	Caulking D	akota	
Ceiling Sheet rockers/Tapers	Concrete Finishers S	iding Crew 13	
Landscapers Tile Setters	Electricians		
Carpenter Others:			
Totals:	13		
Observations – 1) E7: Unit 52 deck door threshold mold and high mitigation continued. Units 49 & 50 back lap siding installation continued. 2) F2: Units 18 & 19 Back windows, trim and foam board installation continued.  Tests/Inspections –  Unresolved Issues/Factors Contributing to Delay –			





Building E7 Units 49 & 50 Back Lap Siding Installation



Building F2 Units 18 & 19 Garage Door Flashing Installation



Building F2 Units 18 & 19 Back Windows Installation



Building F2 Units 18 & 19 Back Window Trim Installation



#### **Daily Observation Report**

Date of Report: Nov 3, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1 REPORT #: 138

ADDRESS: RUNNING BEAR ROAD

ADDRESS: RUNNING BEAR ROAD			
WEATHER			
Temperature	A.M	P.M	
Low Temperature: 25*	Snow	Windy	
High Temperature: 50*	X Mostly Cloudy	Clear	
	Clear	Snow	
CONDITIONS	Other	X Mostly Cloudy	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	Kit 1	
Flooring Roofers	Caulking	Dakota 1	
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew 15	
Landscapers Tile Setters	Electricians		
Carpenter Others:			
Totals:	17		
Observations – 1) E7: Crew worked on site cleanup. 2) F2: Units 18 & 19 Back board and batten siding, blocking, j channel, foam board and knife plate installation continued.  TESTS/INSPECTIONS —  UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —			





Building F2 Units 18 & 19 Back Board and Batten Siding Installation



Building F2 Unit 18 Deck Knife Plates Installation



## **Daily Observation Report**

Date of Report: Nov 4, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1			<b>REPORT #</b> : 139
Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 28*	Snow	Windy	
High Temperature: 57*	X Partly Clo	oudy Clear	
	Clear	Snow	
CONDITIONS	Other	X Partly (	Cloudy
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	Kit	1
Flooring Roofers	Caulking	Dakota	1
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew	16
Landscapers Tile Setters	Electricians	Interior Trim Ca	rpenter 1
Carpenter Others:			
Totals: 19			
Observations – 1) E3: Unit 27 Interior trim installation and finishing. 2) E7: Units 49 & 50 Back corrugated siding installation. 3) F1: Units 16 & 17 Deck GLULAMs painted. 4) F2: Unit 18 Deck knife plates installation. Unit 19 Back deck and lower door installation.			
TESTS/INSPECTIONS —			
UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —			





Building E3 Unit 27 Front Upper Interior Trim Installation and Finishing



Building E7 Units 49 & 50 Back Corrugated Siding Installation



Building F1 & F2 Units 16 - 19 Deck GLULAM's Painted



Building F2 Unit 19 Back Deck and Lower <u>Door Installation</u>



## **Daily Observation Report**

Date of Report: Nov 5, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERI	OR UPGRADES PHASE 1		Report #: 140
Address: Running Bear Road	<b>9.1. 9</b> .1 = 12 = 2		
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 34*	Snow	Windy	
High Temperature: 61*	X Sunny	Clear	
	Clear	Snow	
CONDITIONS	Other	X Sunny	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	Kit	1
Flooring Roofers	Caulking	Dakota	1
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew	15
Landscapers Tile Setters	Electricians	Interior Trim Car	penter 1
Carpenter Others:			
Totals:	18		
Observations – 1) Windows removed from garages and moved to conex box for storage. 2) E3: Unit 27 Interior trim installation and finishing. 3) F1: Units 16 & 17 Deck GLULAMs painted. 4) F2: Units 18 & 19 Back lower doors installed.  TESTS/INSPECTIONS — UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —			





Windows Removed From Garages and Loaded Into Conex For Storage



Windows Removed From Garages and



Building E3 Unit 27 Living Room Trim Installed and Finished



Building F1 & F2 Units 16 - 19 Deck **GLULAM's Painted** 







**Building F2 Unit 18 Back Lower Door Installed** 

**Building F2 Unit 19 Back Lower Door Installed**