

Daily Observation Report

Date of Report: May 2, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

Report #: P2-168

Address: Running Bear Road

WEATHER

TEMPERATURE	A.M	P.M
Low Temperature: 24*	Rain	Windy
High Temperature: 47*	X Cloudy	Clear
	Clear	Rain
Conditions	Other	X Partly Cloudy
CREW ON SITE		
Plasterers Finish Carpenters Finish Carpenters	Plumbers Sid	ding Installers
Flooring Roofers (Caulking D	akota
Ceiling Sheet rockers/Tapers (Concrete Finishers 6 Co	onstruction FA
Landscapers Tile Setters E	Electricians 1 Su	uperintendent
Carpenter Others:	1 N	ICM

Observations – **1)** E8: Unit 56 - 58 front sheathing marked and removed where moisture level exceeded 10%. Substrate tested lower than 10%, unit 56 kitchen window and unit 58 side windows, Tyvek, flashing, gable vent and insulation installed.**2)** Delivery of Building E5 & E6 siding materials

TOTALS: 8

TESTS/INSPECTIONS-



Daily Observation Report

Date of Report: May 3, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

Report #: P2-169

Address: Running Bear Road

WEATHER

TEMPERATURE	A.M	P.M
Low Temperature: 26*	Rain	Windy
High Temperature: 36*	X Snow	Clear
	Clear	Rain
Conditions	Other	X Snow
Crew On Site		
Plasterers Finish Carpenters	Plumbers	Siding Installers
Flooring Roofers	Caulking	Dakota
Ceiling Sheet rockers/Tapers	Concrete Finishers	Construction FA
Landscapers Tile Setters	Electricians	1 Superintendent
Carpenter Others:		1 MCM
Totals:	2	
	2	

Observations - 1) No work due to weather

TESTS/INSPECTIONS-



Daily Observation Report

Date of Report: May 4, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

Report #: P2-170

Address: Running Bear Road

WEATHER

TEMPERATURE	A.M	P.M
Low Temperature: 31*	Rain	Windy
High Temperature: 53*	X Partly Cloudy	Clear
	Clear	Rain
Conditions	Other	X Partly Cloudy
Crew On Site		
Plasterers Finish Carpenters	Plumbers Sic	ling Installers
Flooring Roofers	Caulking Da	akota
Ceiling Sheet rockers/Tapers	Concrete Finishers 7 Co	onstruction FA
Landscapers Tile Setters	Electricians 1 Su	iperintendent
Carpenter Others:	1 M	СМ
Totals:	9	

Observations – **1)** E8: Unit 58 side Tyvek, flashing, gable vent and insulation installed. Units 55 & 56 front Tyvek and windows installed.**2)** Delivery of decking materials.

TESTS/INSPECTIONS-





Bldg E8 Unit 58 Side Wainscot Flashing Installed



Bldg E8 Unit 58 Side Wainscot, Base Flashing & Insulation Installed



Bldg E8 Units 58 Side Ready for Trim, Blocking & Siding



Bdlg E8 Unit 55 Front Window Removed



Bldg E8 Unit 55 Kitchen Window Removed



Bldg E8 Units 55 Kitchen Window, Tyvek Installed





Bldg E8 Unit 56 Front Window Installed



Daily Observation Report

Date of Report: May 5, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

Report #: P2-171

Address: Running Bear Road

WEATHER

TEMPERATURE	A.M	P.M
Low Temperature: 32*	Rain	Windy
High Temperature: 55*	X Partly Cloudy	Clear
	Clear	Rain
Conditions	Other	X Cloudy
CREW ON SITE		
Plasterers Finish Carpenters	Plumbers Si	ding Installers
Flooring Roofers	Caulking D	Dakota
Ceiling Sheet rockers/Tapers	Concrete Finishers 7 C	Construction FA
Landscapers Tile Setters	Electricians 1 S	uperintendent
Carpenter Others:	1 N	ЛСМ
Totals:	9	

Observations – 1) E6: Units 45 - 48 Siding demolition completed.

TESTS/INSPECTIONS-





Building E6 Units 45 - 48 Back Siding Demo



Bldg E6 Units 47 - 48 Front Siding Demo



Bldg E6 Units 45 - 46 Front Siding Demo



Bldg E6 Units 45 - 48 Back Siding Demo



Bldg E6 Units 46 - 47 Front Siding Demo



Daily Observation Report

Date of Report: May 6, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

Report #: P2-172

Address: Running Bear Road

WEATHER

TEMPERATURE	A.M	P.M
Low Temperature: 34*	Rain	Windy
High Temperature: 50*	X Partly Cloudy	Clear
	Clear	Rain
Conditions	Other	X Partly Cloudy
Crew On Site		
Plasterers Finish Carpenters	Plumbers Si	ding Installers
Flooring Roofers	Caulking D	akota
Ceiling Sheet rockers/Tapers	Concrete Finishers 7 C	onstruction FA
Landscapers Tile Setters	Electricians 1 S	uperintendent
Carpenter Others:	1 N	ICM
–	0	
Totals:	9	

Observations – 1) E8: Units 57 & 58 front Tyvek installed. Unit 58 side corrugated wainscot installed. Unit 55 Side & back windows and Tyvek installed

TESTS/INSPECTIONS-





Building E8 Units 57 & 58 Tyvek Installed



Building E8 Unit 58 Wainscot Installed



Building E8 Unit 55 Side Tyvek Installed



Building E8 Unit 55 Back Window & Tyvek Installed





Building E8 Unit 58 Sheathing Removed with Moisture Higher Than 10%



Building E8 Unit 57 Sheathing Removed with Moisture Higher Than 10%



Building E8 Unit 56 Kitchen Window and Tyvek Installed



Building E8 Unit 58 Sheathing Removed with Moisture Higher Than 10%



Building E8 Unit 56 Front Sheathing Removed with Moisture Higher Than 10%



Building E8 Unit 58 Side Insulation and Gable Vent Installed