

# **Daily Observation Report**

Date of Report: May 9, 2022 Prepared By: Jim Goveia

**PROJECT:** BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

**Report #:** P2-173

Address: Running Bear Road

### WEATHER

| TEMPERATURE  | A.M                | P.M               |
|--|--------------------|-------------------|
| Low Temperature: 24*   | Rain               | Windy             |
| High Temperature: 32*  | X Snow             | Clear             |
|  | Clear              | Rain              |
| Conditions   | Other              | X Snow            |
| CREW ON SITE   |                    |                   |
| Plasterers Finish Carpenters                                 | Plumbers           | Siding Installers |
| Flooring Roofers   | Caulking           | Dakota            |
| Ceiling Sheet rockers/Tapers                                 | Concrete Finishers | 0 Construction FA |
| Landscapers Tile Setters                                     | Electricians       | Superintendent    |
| Carpenter Others:  |                    | МСМ               |
| Totals:  | 0                  |                   |
| Observations – No work due to weather<br>Tests/Inspections – |                    |                   |

**UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY** – None



# **Daily Observation Report**

Date of Report: May 10, 2022 Prepared By: Jim Goveia

**PROJECT:** BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

**Report #:** P2-174

ADDRESS: RUNNING BEAR ROAD

#### WEATHER

| TEMPERATURE                  | A.M            | P.M  |
|------------------------------|----------------|--|
| Low Temperature: 16*         | Rain           | Windy  |
| High Temperature: 43*        | X Sunny        | Clear  |
| Conditions                   | Clear<br>Other | <ul><li>Rain</li><li>X Partly Cloudy</li></ul> |
| CREW ON SITE                 |                |  |
| Plasterers Finish Carpenters | Plumbers       | Siding Installers                              |
| Flooring Roofers             | Caulking       | Dakota   |

| Ceiling     | Sheet rockers/Tapers | . <u> </u> | Concrete Finishers | 6 | Construction FA |
|-------------|----------------------|------------|--------------------|---|-----------------|
| Landscapers | Tile Setters         |            | Electricians       | 1 | Superintendent  |
| Carpenter   | Others:              |            |                    | 1 | МСМ             |
|             |                      | TOTALS:    | 8                  |   |                 |
|             |                      |            |                    |   |                 |

**Observations** – E8: Unit 57 ledger blocking is in progress. Unit 58; ledger blocking is complete; wainscot on gable end is complete; new front soffit is in progress. Drain wrap at front of building for all Units #55-58 is approx. 85% complete. New garage door jambs for Units #55 - #58 are in progress.

E6: All removal of wood siding is complete.

**TESTS/INSPECTIONS** – Site visit from Architect of Record to review progress - no issues or concerns raised or identified.

UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY - None



# **Daily Observation Report – cont.**

**PROGRESS OF WORK (PHOTOS)** 



Building E8 Units 55 & 56 Garage Door Trim



Building E8 Unit #58 Blocking at Deck



Building E8 Unit #57 Blocking in Progress



Building E8 Unit #58 Soffit in Progress



# **Daily Observation Report**

Date of Report: May 11, 2022 Prepared By: Jim Goveia

**PROJECT:** BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

**Report #:** P2-175

Address: Running Bear Road

### WEATHER

| TEMPERATURE                  | A.M                     | P.M             |
|------------------------------|-------------------------|-----------------|
| Low Temperature: 21*         | Rain                    | Windy           |
| High Temperature: 49*        | X Sunny                 | Clear           |
|                              | Clear                   | Rain            |
| Conditions                   | Other                   | X Partly Cloudy |
| Crew On Site                 |                         |                 |
| Plasterers Finish Carpenters | Plumbers Sig            | ding Installers |
| Flooring Roofers             | Caulking D              | akota           |
| Ceiling Sheet rockers/Tapers | Concrete Finishers 7 Co | onstruction FA  |
| Landscapers Tile Setters     | Electricians 1 Su       | uperintendent   |
| Carpenter Others:            | 1 N                     | 1CM             |

TOTALS: 9

**Observations** – E8: Unit 57 ledger blocking is complete. Sheathing for units 56-58 was installed. Belly band at units 55 and 56 was completed.

**TESTS/INSPECTIONS-**

UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY -



PROGRESS OF WORK (PHOTOS)



Building E8 Unit #55 Blocking in Progress



Building E8 Unit #57 Sheathing Complete



**Building E8 Unit #56 Sheathing Complete** 



Building E8 Unit #58 Sheathing Complete



Building E8 Unit #56 Belle Band



Building E8 Units 57 & 56 Kitchen Windows



# **Daily Observation Report**

Date of Report: May 12, 2022 Prepared By: Jim Goveia

**PROJECT:** BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

**Report #:** P2-176

Address: Running Bear Road

### WEATHER

| TEMPERATURE                  | A.M                     | P.M             |
|------------------------------|-------------------------|-----------------|
| Low Temperature: 34*         | Rain                    | Windy           |
| High Temperature: 45*        | X Snowy                 | Clear           |
|                              | Clear                   | Rain            |
| Conditions                   | Other                   | X Snowy         |
| Crew On Site                 |                         |                 |
| Plasterers Finish Carpenters | Plumbers Sig            | ding Installers |
| Flooring Roofers             | Caulking D              | akota           |
| Ceiling Sheet rockers/Tapers | Concrete Finishers 3 Co | onstruction FA  |
| Landscapers Tile Setters     | Electricians 1 Su       | uperintendent   |
| Carpenter Others:            | 1 N                     | ICM             |

TOTALS: 5

**Observations** – E8: Tyvek drain wrap was installed at Unit 55 backside. Belly band was installed at Units 58 & 57. Soffit installation on back side has started at Units 55 - 57.

**TESTS/INSPECTIONS-**

UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY -



PROGRESS OF WORK (PHOTOS)



Building E8 Unit 58 & 57 Belly Band



Building E8 Unit 55 Drain Wrap



Building E8 Unit 55 Rear Soffit



Building E8 Unit 56 & 57 Rear Soffit



## **Daily Observation Report**

Date of Report: May 13, 2022 Prepared By: Jim Goveia

**PROJECT:** BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

**Report #:** P2-177

Address: Running Bear Road

#### WEATHER

| TEMPERATURE                    | A.M                     | P.M             |
|--------------------------------|-------------------------|-----------------|
| Low Temperature: 22*           | Rain                    | Windy           |
| High Temperature: 46*          | X Snow                  | Clear           |
|                                | Clear                   | Rain            |
| Conditions                     | Other                   | X Partly Cloudy |
| Crew On Site                   |                         |                 |
| Plasterers Finish Carpenters I | Plumbers Sig            | ding Installers |
| Flooring Roofers 0             | Caulking Da             | akota           |
| Ceiling Sheet rockers/Tapers ( | Concrete Finishers 7 Co | onstruction FA  |
| Landscapers Tile Setters I     | Electricians 1 Pr       | oject Manager   |
| Carpenter Others:              | 1 M                     | CM              |

**Observations** – **1)** E8: Units 56 - 58 front base & wainscot flashing, insulation, installed. Unit 58 front corrugated wainscot installed. Units 56 & 57 kitchen window flashing and trim installed. **2)** E9: Units 61 - 64 performed pre-construction existing conditions survey.


TOTALS: 9

**TESTS/INSPECTIONS**-

UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY -



**PROGRESS OF WORK (PHOTOS)** 



**Delivery of Building E6 Siding Materials** 



Building E8 Unit 58 Sheathing Removed with Moisture Higher Than 10%



Building E8 Unit 57 Front Sheathing Removed with Moisture Higher Than 10%



Building E8 Unit 58 Sheathing Removed with Moisture Higher Than 10%



Building E8 Unit 57 Sheathing Removed with Moisture Higher Than 10%



Building E8 Unit 56 Front Sheathing Removed with Moisture Higher Than 10%