

Daily Observation Report

Date of Report: June 13, 2022 Prepared By: Jim Goveia

1 MCM

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

Report #: P2-197

Address: Running Bear Road

WEATHER

TEMPERATURE	A.M	P.M
Low Temperature: 34*	Rain	Windy
High Temperature: 46*	X Rain	Clear
	Clear	Snow
Conditions	Other	X Rain
CREW ON SITE		
Plasterers Finish Carpenters	Plumbers Sig	ding Installers
Flooring Roofers	Caulking Da	akota
Ceiling Sheet rockers/Tapers	Concrete Finishers 1 Co	onstruction FA
Landscapers Tile Setters	Electricians 1 Su	uperintendent

TOTALS: 3

Observations - 1) E6: Units 45 - 48 window & garage door trim installed.

TESTS/INSPECTIONS-

Carpenter

UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY -

Others:





Building E6 Units 45 - 48 Garage Door Trim Installed



Daily Observation Report

Date of Report: June 14, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

Report #: P2-198

Address: Running Bear Road

WEATHER

TEMPERATURE	E	A.M	P.M
Low	Temperature: 30*	Rain	Windy
High	Temperature: 45*	X Snow/Cloudy/ Windy	Clear
		Clear	Snow
CONDITIONS		Other	X Snow/Cloudy/ Windy
CREW ON SITE	E		
Plasterers	Finish Carpenters	Plumbers	Siding Installers

Plasterers	Finish Carpenters	Plumbers		Siding Installers
Flooring	Roofers	Caulking		Dakota
Ceiling	Sheet rockers/Tapers	Concrete Finishers	14	Construction FA
Landscapers	Tile Setters	Electricians	1	Superintendent
Carpenter	Others:		1	МСМ
	TOTALS:	16		

Observations – **1)** C5: Units 39 - 40 window installation began. **2)** E6: Units 45 - 48 corrugated & lap siding installation began. window & garage door trim installation continued. **3)** E9: Units 61 - 63 Deck & Front doors installed.

TESTS/INSPECTIONS-

UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY -





Building C5 Unit 40 Side Upper Window Installed



Building E6 Unit 48 Side Lap Siding Installed



Building E6 Units 46 & 47 Back Corrugated Siding Installed



Building E9 Units 62 & 63 Deck Door Installed



Daily Observation Report

Date of Report: June 15, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

Report #: P2-199

ADDRESS: RUNNING BEAR ROAD

WEATHER

TEMPERATURE		A.M	P.M
Low T	emperature: 34*	Rain	Windy
High 1	Femperature: 62*	X Partly Cloudy	Clear
		Clear	Snow
CONDITIONS		Other	X Partly Cloudy
CREW ON SITE			
Plasterers	Finish Carpenters	Plumbers	Siding Installers

Plasterers	Finish Carpenters		Plumbers		Siding Installers
Flooring	Roofers		Caulking		Dakota
Ceiling	Sheet rockers/Tapers		Concrete Finishers	16	Construction FA
Landscapers	Tile Setters		Electricians	1	Superintendent
Carpenter	Others:			1	MCM
	Τοτα	LS:	18		

Observations – **1)** C5: Unit 39 windows installed. **2** D: Units 36 - 38 window installation began. **3)** E6: Units 45 - 48 corrugated, lap & snap batten siding, j channel trim block out installation continued. 4) E9: Units 62 & 63 garage doors installed.

TESTS/INSPECTIONS-

UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY -





Building C5 Unit 39 Side Windows Removed



Building E6 Units 46 & 47 Front Corrugated and Lap Siding Installed



Building D Unit 36 Side Windows Installed



Building E6 Units 45 & 46 Front Snap Batten Siding Installed



Daily Observation Report

Date of Report: June 16, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

Report #: P2-200

Address: Running Bear Road

WEATHER

TEMPERATURE	A.M	P.M	
Low Temperature: 31*	Rain	Windy	
High Temperature: 77*	X Sunny	Clear	
	Clear	Snow	
CONDITIONS	Other	X Sunny	

CREW ON SITE

Ceiling	Sheet rockers/Tapers			 Construction FA
Landscapers Carpenter	Others:		Electricians	Superintendent MCM
	-	Totals:	21	

Observations – **1)** D: Units 36 - 38 window installation continued. Units 37 & 38 front doors installed. **2)** E5: Units 41 - 44 front doors installed. **3)** E6: Unit 46 garage door installed. Units 45 - 48 corrugated, lap & snap batten siding continued. **4)** E9: Unit 64 garage doors installed.

TESTS/INSPECTIONS-

UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY -





Building D Unit 38 Side Windows Installed



Building D Units 37 & 38 Back Windows Installed



Building E5 Unit 42 Front Door Installed



Building E6 Units 45 & 46 Front Corrugated Siding and Garage Door Installed





Building E6 Units 47 & 48 Front Snap Batten Siding Installed



Building E6 Units 45 & 46 Back Lap Siding Installed