

BACKFLOW PREVENTER FIELD TEST MAINTENANCE REPORT

| CUSTOMER: | PHONE: | | |
|--|----------------|----------------------------------|--|
| ADDRESS OF PROPERTY: Crack 601-604 | | | |
| MAILING ADDRESS: | | | |
| CITY: Big Sky STATE: MT ZIP CODE: | | | |
| MFTER NUMBER: SÉRVICE NUMBER: WHA | | | |
| PURPOSE OF PROTECTION: METER IRRIGATION FIRES TOTHER | | | |
| ASSEMBLY TYPE: PRP IDC IPVB ISPBV | | | |
| MAKE: Fetro MODEL: 8257 SIZE: 149 | | | |
| SERIAL NUMBER: 1908609 LOCATION OF ASSEMBLY: Basement of Unit Ugus PACC | | | |
| LOCATION OF ASSEMBLY: Basement of Unit Want pace | | | |
| · | | | |
| CONTAINMENT ISOLATION LINE PRESSURE: | | | |
| RP/DC | RP/DC | RP | PRESSURE VACUUM |
| CHECK VALVE #1 | CHECK VALVE #2 | RELIEF VALVE | BREAKER |
| INITIAL TEST | INITIAL TEST | INITIAL TEST OPENED @ 24 PSID | INITIAL TEST AIR INLET OPENED @PSID |
| LEAKED | LEAKED | DID NOT OPEN | DID NOT OPEN |
| PSID PSID | CLOSED TIGHT | | CHECK VALVE LEAKED |
| PSID_ONG | PSID | 12 | HELD @PSID |
| CLEANED | CLEANED | CLEANED | CLEANED |
| REPLACED | REPLACED | REPLACED | REPLACED |
| RUBBER KIT | RUBBER KIT | RUBBER KIT | RUBBER KIT |
| DISC | DISC | DISC | DISC |
| 0-RING | O-RING | O-RING | O-RING |
| SEAT | SEAT | SEAT | SEAT 🗍 |
| SPRING | SPRING | SPRING | SPRING |
| OTHER: | OTHER: | DIAPHRAGM | OTHER: |
| | | OTHER: | |
| FINAL TEST | FINAL TEST | FINAL TEST OPENED @ Z PSID | FINAL TEST AIR INLET OPENED @ PSID |
| LEAKED | LEAKED | DID NOT OPEN | AIR INLET OPENED @PSID DID NOT OPEN |
| CLOSED TIGHT | CLOSED TIGHT | DID NOT OPEN | DID NOT OF EN |
| PSIDE _ | PSID | | |
| PASSED FAILED PROPERLY INSTALLED | | | |
| COMMENTS: | | | |
| I CERTIFY THE ABOVE INFORMATION IS TRUE AND ACCURATE AT THE TIME OF TESTING. | | | |
| TESTER NAME: Michael Ditch - 27-377 DATE: 10-11-2-22 | | | |
| COMPANY NAME: IT&M Division Inc | | | |
| ADDRESS: PO Box 5868, Helena MT 59604 | | | |
| PHONE NUMBER: (406 | 6) 495-1543 | FAX NUMBER | R: (406) 443-3578 |
| SIGNATURE: | | | |