

## **Daily Observation Report**

Date of Report: June 28, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1

**REPORT #**: 047

Address: Running Bear Road		
WEATHER		
TEMPERATURE	A.M	P.M
Low Temperature: 49*	Snow	Windy
High Temperature: 79*	X Sunny	Clear
	Clear	Snow
CONDITIONS	Other	X Sunny
CREW ON SITE		
Plasterers Finish Carpenters	Plumbers	Window Installers
Flooring Roofers	Caulking	Insulation
Ceiling Sheet rockers/Tapers	Concrete Finishers	Framing Crew
Landscapers Tile Setters	Electricians	Crew 3
Painters Others:		
Totals:	3	
OBSERVATIONS — 1) E3: Cutting in gable vents. 2) F1: Unit #17 Sheathing is complete on side next to front door. Building wrap in progress for deck side.  TESTS/INSPECTIONS — None  UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY — Minimal workers are present as crew is in transition of replacing workers.		



## **Daily Observation Report – cont.**



**Building E3 Unit 24 & 25 Cut In Vents** 



**Building E3 Unit 26 & 27 Cut In Vents** 



**Building F1 Unit 17 Sheathing Replacement** 



# **Daily Observation Report**

Date of Report: June 29, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1	<b>Report #</b> : 048
Address: Running Bear Road	

WEATHER		
TEMPERATURE	A.M	P.M
Low Temperature: 48*	Snow	Windy
High Temperature: 82*	X Partly Cloudy	Clear
	Clear	Snow
CONDITIONS	Other	X Partly Cloudy
CREW ON SITE		
Plasterers Finish Carpenters	Plumbers	Window Installers
Flooring Roofers	Caulking	Insulation
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew 6
Landscapers Tile Setters3	Electricians	Interior Trim Crew 2
Painters Others:		
Totals:	8	
OBSERVATIONS – 1) E3: Units 24 & 25 gable vents cut in. 2) F1: Unit #17 Kitchen window installed. Units 16 & 17 Continued Demo, Tyvek installation, Window installation at basement, upper deck railing blocking installation.		
<b>TESTS/INSPECTIONS</b> – SE inspected upper deck railing blocking, instructed contractor to use recommended nails and ensure proper attachment.		
UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DEL	AY —	



## Daily Observation Report - cont.



**Building E3 Unit 24 & 25 New Attic Vents Cut In** 



**Building F1 Unit 17 Kitchen Window Installed** 



**Building F1 Unit 16 & 17 Demo Continued** 



Bldg F1 Unit 16 & 17 Tyvek Install Continued



**Bldg F1 Unit 16 Basement Left Window Installed** 



Bldg F1 Unit 16 Upper Deck Railing
Blocking Location Cut Out



## **Daily Observation Report**

Date of Report: June 30, 2021 Prepared By: Jim Goveia

<b>PROJECT:</b> BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1	<b>Report #</b> : 049

Address: Running Bear Road		
WEATHER		
TEMPERATURE	A.M	P.M
Low Temperature: 48*	Snow	Windy
High Temperature: 82*	X Sunny	Clear
	Clear	Snow
CONDITIONS	Other	X Sunny
CREW ON SITE		
Plasterers Finish Carpenters	Plumbers	Window Installers
Flooring Roofers	Caulking	Insulation
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew 6
Landscapers Tile Setters	Electricians	Interior Trim Crew 2
Painters Others:		
Totals:	8	
OBSERVATIONS – F1: Unit #16 & 17 Continued Tyvek installation, Window and Flashing Tape installation.		
TESTS/INSPECTIONS – None		
Unresolved Issues/Factors Contributing to Delay –		






**Building F1 Unit 16 & 17 Window Installation** 



**Building F1 Unit 16 Upper Deck Railing Blocking** 



**Building F1 Unit 16 & 17 Demo Continued** 



**Building F1 Unit 17 Deck Brackets Removed** 



#### **Daily Observation Report**

Partly Cloudy

Date of Report: July 1, 2021 Prepared By: Jim Goveia

<b>PROJECT:</b> BIG HORN CONDO SIDING REPLACEMENT & EX	<b>Report #</b> : 050	
Address: Running Bear Road		
<b>W</b> EATHER		
<b>T</b> EMPERATURE	A.M	P.M
Low Temperature: 52*	Snow	Windy
High Temperature: 81*	X Partly Cloudy	Clear
	Clear	Snow

Other

# CREW ON SITE Plasterers \_\_\_\_\_ Finish Carpenters \_\_\_\_\_ Plumbers \_\_\_\_\_ Window Installers

Flooring \_\_\_\_ Roofers \_\_\_ Caulking \_\_\_ Insulation \_\_\_\_

Ceiling \_\_\_ Sheet rockers/Tapers \_\_\_ Concrete Finishers \_\_\_ Siding Crew 4

Landscapers Tile Setters Electricians Interior Trim Crew 2

Painters \_\_\_\_ Others:

**CONDITIONS** 

Totals: 6

OBSERVATIONS — E7: Unit #49 & 52 Continued siding demo.

TESTS/INSPECTIONS — None

UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —



## Daily Observation Report - cont.



**Building F1 Unit 16 Kitchen Window Installed** 



**Building F1 Unit 17 Rear Upper Window Installed** 



**Building E7 Unit 49 Demo Continues** 



**Building E7 Unit 49 & 50 Demo** 



## **Daily Observation Report**

Date of Report: July 2, 2021 Prepared By: Jim Goveia

**PROJECT:** BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1 **REPORT #**: 051

Address: Running Bear Road		
WEATHER		
TEMPERATURE	A.M	P.M
Low Temperature: 46*	Snow	Windy
High Temperature: 81*	X Partly Cloudy	Clear
	Clear	Snow
CONDITIONS	Other	X Partly Cloudy
CREW ON SITE		
Plasterers Finish Carpenters	Plumbers	Window Installers
Flooring Roofers	Caulking	Insulation
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew 8
Landscapers Tile Setters	Electricians	Interior Trim Crew 2
Painters Others:		
TOTALS:	10	
OBSERVATIONS – 1) E3: unit 27 Interior Window Polymer Urethane Finish Application. 2) E7: Unit #49 Deck pier brackets removed. Unit #50 & 51 Continued siding demo. Units 49 & 50 Deck Blocking delineated.  TESTS/INSPECTIONS – None		
Unresolved Issues/Factors Contributing to Delay –		



## **Daily Observation Report – cont.**



Building E3 Unit 27 Lower Back Window Urethane Application



**Building E7 Unit 49 Deck Blocking Area Defined** 



Building E7 Unit 49 Deck
Pier Bracket Removed



Building E7 Unit 50 Deck Pier Blocking Area Defined