

# **Daily Observation Report**

Date of Report: Sept. 7, 2021 Prepared By: Jim Goveia

			- "		
PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERI	OR UPGRADES PHASE 1		<b>REPORT #</b> : 097		
Address: Running Bear Road					
WEATHER					
TEMPERATURE	A.M	P.M			
Low Temperature: 43*	Snow	Windy			
High Temperature: 84*	X Sunny	Clear			
	Clear	Snow			
CONDITIONS	Other	X Sunny			
Crew On Site					
Plasterers Finish Carpenters	Plumbers	Kit	1		
Flooring Roofers	Caulking	Dakota	1		
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew	24		
Landscapers Tile Setters	Electricians				
Carpenter Others:					
Totals:	26				
Observations – 1) E1: Units 8 - 11 front lap and corrugated siding installation continued. 2) E2: Units 20 - 23 wainscoting & base flashing installation. 3) E4: Units 28 - 31 corrugated & lap siding installation continued.  Tests/Inspections –  Unresolved Issues/Factors Contributing to Delay –					



### **Daily Observation Report – cont.**



Building E1 Units 8 & 9 Front Lap Siding Installed



**Building E1 Unit 8 Corrugated Siding Installed** 



Building E4 Unit 31 & 30 Front Corrugated Siding Installed



Building E4 Units 30 & 29 Front Lap Siding Installed



Building E4 Units 28 & 29 Front Lap Siding Installed



Building E2 Unit 23 Wainscoting & Base Flashing Installation



# **Daily Observation Report**

Date of Report: Sept. 8, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXT	erior Upgrades Phase 1		<b>Report #</b> : 098		
Address: Running Bear Road					
WEATHER					
TEMPERATURE	A.M	P.M			
Low Temperature: 46*	Snow	Windy			
High Temperature: 91*	X Sunny	Clear			
	Clear	Snow			
CONDITIONS	Other	X Sunny			
Crew On Site					
Plasterers Finish Carpenters	_ Plumbers	Kit	1		
Flooring Roofers	_ Caulking	Dakota	1		
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew	24		
Landscapers Tile Setters	_ Electricians				
Carpenter Others:					
Totals	: 26				
Observations – 1) E1: Units 8 - 11 front board and batten installation continued. 2) E2: Units 20 - 23 front foam board, soffit & windows and door trim installation. 3) E4: Units 28 - 31 corrugated & lap siding installation continued.  Tests/Inspections –  Unresolved Issues/Factors Contributing to Delay –					



### **Daily Observation Report - cont.**



Building E1 Units 8 & 9 Board and Batten Siding Installation



Building E2 Units 20 & 21 Foam Board & Door and Window Trim Installation



Building E2 Units 21 & 22 Front Eve Soffit Vents Cut In



Building E4 Units 30 & 31 Corrugated & Board and Batten Siding Installation



# **Daily Observation Report**

Date of Report: Sept. 9, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTER	IOR UPGRADES PHASE 1		<b>REPORT #</b> : 099		
Address: Running Bear Road					
WEATHER					
TEMPERATURE	A.M	P.M			
Low Temperature: 48*	Snow	Windy			
High Temperature: 86*	X Sunny	Clear			
	Clear	Snow			
CONDITIONS	Other	X Sunny			
Crew On Site					
Plasterers Finish Carpenters	Plumbers	Kit	1		
Flooring Roofers	Caulking	Dakota	1		
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew	24		
Landscapers Tile Setters	Electricians				
Carpenter Others:					
Totals:	26				
Observations — 1) E1: Units 10 - 11 front lap siding installation continued. 2) E2: Units 20 - 23 J channel, soffit & windows and door trim installation continued. 3) E4: Units 28 - 29 deck doors installed. Units 28 - 31 lap siding installation continued.  TESTS/INSPECTIONS —  UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —					



### **Daily Observation Report - cont.**



Building E1 Units 8 & 9 Front Board and Batten Siding Installation



Building E1 Units 10 & 11 Front Lap Siding Installation



Building E2 Units 20 & 21 Front J Channel and Corrugated Siding Installation



**Building E4 Unit 29 Deck Door Installation** 



**Building E4 Unit 28 Side Lap Siding Installation** 



Building E4 Unit 29 Front Lap Siding Installation



# **Daily Observation Report**

Date of Report: Sept. 10, 2021 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 1					
Address: Running Bear Road	ON OPGINALES I HASE I		REPORT #: 100		
WEATHER					
TEMPERATURE	A.M	P.M			
Low Temperature: 48*	Snow	Windy			
High Temperature: 79*	X Mostly Cloudy	Clear			
	Clear	Snow			
CONDITIONS	Other	X Mostly	/ Cloudy		
CREW ON SITE					
Plasterers Finish Carpenters	Plumbers	Kit	1		
Flooring Roofers	Caulking	Dakota	1		
Ceiling Sheet rockers/Tapers	Concrete Finishers	Siding Crew	25		
Landscapers Tile Setters	Electricians				
Carpenter Others:					
Totals:	27				
Observations – 1) E1: Units 10 - 11 front board and batten siding installation continued. Units 9 & 10 deck fill dirt installation. 2) E2: Units 20 - 23 J channel, soffit & corrugated siding installation continued. 3) E4: Units 28 - 31 deck door trim and J channel installed.  TESTS/INSPECTIONS —  UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —					
UNKESULVED ISSUES/ FACTORS CONTRIBUTING TO DELAY —					



### Daily Observation Report - cont.



Building E1 Units 10 & 11 Board and Batten Siding Installation



**Building E1 Units 9 & 10 Fill Dirt Installation** 



Building E2 Unit 20 Corrugated
Siding Installation



**Building E4 Unit 28 Deck Door Installation**