

Daily Observation Report

Date of Report: Oct 10, 2022 Prepared By: Jim Goveia

5 11 2 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		P # 02 270			
PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTER	IOR UPGRADES PHASE 2	REPORT # : P2-278			
Address: Running Bear Road					
WEATHER					
TEMPERATURE	A.M	P.M			
Low Temperature: 34*	Snow	Windy			
High Temperature: 71*	X Sunny	Clear			
	Clear	Snow			
CONDITIONS	Other	X Sunny			
CREW ON SITE					
Plasterers Finish Carpenters	Plumbers	0 Radon System Installers			
Flooring Roofers 0	Concrete Coating Installer	2 Railing Installers			
Ceiling Sheet rockers/Tapers 0	Phase 1 punch list crew 1	3 Construction FA			
Landscapers Tile Setters 0	Laborers	1 Superintendent			
Carpenter Others: 0	Helical Pier Installers	1 MCM			
Totals:	13				
Observations – 1) B: Units 3 - 7 Back lap siding installation continued. Front corrugated siding installation continued. 2) C3: Unit 33 deck railing installed. Observed Simpson brackets missing. 3) C4: Units 34 & 35 back snap batten, lap siding & soffit installation continued. Front corrugated siding and soffit continued. Observed soffit vent holes not drilled. 4) C5: Unit 40 deck railing installed. Observed Simpson brackets missing. TESTS/INSPECTIONS – UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –					





Building B Units 3 - 7 Lap Siding Installed



Building B Units 6 - 7 Corrugated Siding Installed



Building C4 Unit 34 Snap Batten & Lap Siding Installed



Building C4 Unit 34 Soffit Installed





Building C4 Units 34 & 35 Front & Garage Door Trim & J Channel Installed



Building C5 Unit 40 Deck Railing Installed



Daily Observation Report

Date of Report: Oct 11, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2 **REPORT #: P2-279 ADDRESS:** RUNNING BEAR ROAD **W**EATHER **TEMPERATURE** A.M P.M Low Temperature: 31* Snow Windy High Temperature: 57* Cloudy/Rain/Hail Clear Clear Snow **CONDITIONS** Other Mostly Sunny **CREW ON SITE** Plasterers Finish Carpenters Plumbers 0 Radon System Installers Flooring Roofers O Concrete Coating Installer 2 Railing Installers 0 Phase 1 punch list crew Ceiling Sheet rockers/Tapers 13 Construction FA Tile Setters Landscapers 0 Laborers 1 Superintendent 2 Helical Pier Installers 1 MCM Carpenter Others: TOTALS: 19 Observations – 1) A: Units 1 & 2 Deck helical piers relocated. Back lap siding installation began. 2) B: Units 3 - 7 Back lap siding & fascia installation continued. Front corrugated siding installation continued. 3) C3: Unit 33 deck railing installation completed. Observed Simpson brackets missing. 4) C4: Units 34 & 35 Front corrugated siding continued. 5) C10: Units 69 & 70 deck railing installed. Observed Simpson brackets missing. Decking installation began. 6) E7: Unit 52 Deck framing continued and decking & fascia installed. TESTS/INSPECTIONS -UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY -





Building A Units 1 & 2 Deck Helical Piers Relocated & Back Lap Siding Installation Began



Building B Units 1 - 7 Back Lap Siding Installation Continued



Building B Unit 7 Back Fascia Installed



Building C3 Unit 33 Deck Railing Installed



Building C10 Unit 69 Deck Railing & Decking Installed



Building C10 Unit 70 Deck Railing Installed





Building E7 Unit 52 Deck Framing Continued & Fascia & Decking Installed



Daily Observation Report

Date of Report: Oct 12, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT &	& Exterior Upgrades Phase 2	Report #: P2-280

ADDRESS: RUNNING BEAR ROAD





Building B Units 1 & 2 Deck Framing Continued & Back Lap Siding Installation Continued



Building A Units 3 - 7 Back Fascia & Lap Siding Installation Completed



Building B Unit 3 Side Electrical Panel Painted



Building C3 Unit 33 Decking Installation Completed



Building C3 Unit 32 Decking Installed



Building C4 Units 34 & 35 Front Diverters, Corrugated & Lap Siding Installed





Building C7 Unit 60 Side Radon System Exhaust Penetration



Building E7 Unit 52 Side Radon System Exhaust Installed



Daily Observation Report

Date of Report: Oct 13, 2022 Prepared By: Jim Goveia

MEATHER TEMPERATURE	PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTER	Report # : P2-281					
TEMPERATURE Low Temperature: 32* Snow Windy High Temperature: 68* X Mostly Sunny Clear Clear Snow Other X Mostly Sunny CREW ON SITE Plasterers Finish Carpenters Plumbers 2 Radon System Installers Flooring Roofers 0 Concrete Coating Installer 0 Railing Installers Ceiling Sheet rockers/Tapers 0 Phase 1 punch list crew 12 Construction FA Landscapers Tile Setters 2 Painters 1 Superintendent Carpenter Others: 0 Helical Pier Installers 1 MCM Totals: 18 Observations - 1) A: Units 1 & 2 Deck framing continued. Back lap siding installation continued 2) B: Units 3 - 7 Front fascia installation continued. 3) C4: Units 34 & 35 Crawl space radon reduction system installed. 4) E8: Units 55, 56 & 58 Deck railing installed. TESTS/INSPECTIONS -	Address: Running Bear Road						
Low Temperature: 32*	WEATHER						
High Temperature: 68* X Mostly Sunny Clear Clear Clear Clear Now Conditions Crew On Site Plasterers Finish Carpenters Plumbers Plumbers 2 Radon System Installers Flooring Roofers 0 Concrete Coating Installer 0 Railing Installers Ceiling Sheet rockers/Tapers 0 Phase 1 punch list crew 12 Construction FA Landscapers Tile Setters 2 Painters 1 Superintendent Carpenter Others: 0 Helical Pier Installers 1 MCM TOTALS: 18 Cobservations - 1) A: Units 1 & 2 Deck framing continued. Back lap siding installation continued 2) B: Units 3 - 7 Front fascia installation continued. 3) C4: Units 34 & 35 Crawl space radon reduction system installed. 4) E8: Units 55, 56 & 58 Deck railing installed. TESTS/INSPECTIONS -	TEMPERATURE	A.M	P.	.M			
CONDITIONS CREW ON SITE Plasterers Finish Carpenters Plumbers 2 Radon System Installers Flooring Roofers 0 Concrete Coating Installer 0 Railing Installers Ceiling Sheet rockers/Tapers 0 Phase 1 punch list crew 12 Construction FA Landscapers Tile Setters 2 Painters 1 Superintendent Carpenter Others: 0 Helical Pier Installers 1 MCM TOTALS: 18 Observations - 1) A: Units 1 & 2 Deck framing continued. Back lap siding installation continued 2) B: Units 3 - 7 Front fascia installation continued. 3) C4: Units 34 & 35 Crawl space radon reduction system installed. 4) E8: Units 55, 56 & 58 Deck railing installed. TESTS/INSPECTIONS -	Low Temperature: 32*	Snow] Windy			
CREW ON SITE Plasterers Finish Carpenters Plumbers 2 Radon System Installers Flooring Roofers 0 Concrete Coating Installer 0 Railing Installers Ceiling Sheet rockers/Tapers 0 Phase 1 punch list crew 12 Construction FA Landscapers Tile Setters 2 Painters 1 Superintendent Carpenter Others: 0 Helical Pier Installers 1 MCM TOTALS: 18 Observations - 1) A: Units 1 & 2 Deck framing continued. Back lap siding installation continued 2) B: Units 3 - 7 Front fascia installation continued. 3) C4: Units 34 & 35 Crawl space radon reduction system installed. 4) E8: Units 55, 56 & 58 Deck railing installed. TESTS/INSPECTIONS -	High Temperature: 68*	X Mostly Sun	ny [] Clear			
CREW ON SITE Plasterers Finish Carpenters Plumbers		Clear		Snow			
Plasterers Finish Carpenters Plumbers 2 Radon System Installers Flooring Roofers 0 Concrete Coating Installer 0 Railing Installers Ceiling Sheet rockers/Tapers 0 Phase 1 punch list crew 12 Construction FA Landscapers Tile Setters 2 Painters 1 Superintendent Carpenter Others: 0 Helical Pier Installers 1 MCM TOTALS: 18 Observations - 1) A: Units 1 & 2 Deck framing continued. Back lap siding installation continued 2) B: Units 3 - 7 Front fascia installation continued. 3) C4: Units 34 & 35 Crawl space radon reduction system installed. TESTS/INSPECTIONS -	CONDITIONS	Other	X	Mostly Sunny			
Flooring Roofers	CREW ON SITE						
Ceiling Sheet rockers/Tapers 0 Phase 1 punch list crew 12 Construction FA Landscapers Tile Setters 2 Painters 1 Superintendent Carpenter Others: 0 Helical Pier Installers 1 MCM TOTALS: 18 Observations - 1) A: Units 1 & 2 Deck framing continued. Back lap siding installation continued 2) B: Units 3 - 7 Front fascia installation continued. 3) C4: Units 34 & 35 Crawl space radon reduction system installed. 4) E8: Units 55, 56 & 58 Deck railing installed. TESTS/INSPECTIONS -	Plasterers Finish Carpenters	Plumbers	2 Rador	System Installers			
Landscapers Tile Setters 2 Painters 1 Superintendent Carpenter Others: 0 Helical Pier Installers 1 MCM TOTALS: 18 Observations - 1) A: Units 1 & 2 Deck framing continued. Back lap siding installation continued 2) B: Units 3 - 7 Front fascia installation continued. 3) C4: Units 34 & 35 Crawl space radon reduction system installed. 4) E8: Units 55, 56 & 58 Deck railing installed. TESTS/INSPECTIONS -	Flooring Roofers 0	Concrete Coating Installer	0 Railin	g Installers			
Carpenter Others: 0 Helical Pier Installers 1 MCM Totals: 18 Observations – 1) A: Units 1 & 2 Deck framing continued. Back lap siding installation continued 2) B: Units 3 - 7 Front fascia installation continued. 3) C4: Units 34 & 35 Crawl space radon reduction system installed. 4) E8: Units 55, 56 & 58 Deck railing installed. Tests/Inspections –	Ceiling Sheet rockers/Tapers 0	Phase 1 punch list crew	12 Const	ruction FA			
Totals: 18 Observations – 1) A: Units 1 & 2 Deck framing continued. Back lap siding installation continued 2) B: Units 3 - 7 Front fascia installation continued. 3) C4: Units 34 & 35 Crawl space radon reduction system installed. 4) E8: Units 55, 56 & 58 Deck railing installed. Tests/Inspections –	Landscapers Tile Setters 2	Painters	1 Super	intendent			
Observations – 1) A: Units 1 & 2 Deck framing continued. Back lap siding installation continued 2) B: Units 3 - 7 Front fascia installation continued. 3) C4: Units 34 & 35 Crawl space radon reduction system installed. 4) E8: Units 55, 56 & 58 Deck railing installed. TESTS/INSPECTIONS –	Carpenter Others: 0	Helical Pier Installers	1 MCM				
 3 - 7 Front fascia installation continued. 3) C4: Units 34 & 35 Crawl space radon reduction system installed. 4) E8: Units 55, 56 & 58 Deck railing installed. TESTS/INSPECTIONS — 	Totals: 18						
UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –							





Building A Units 1 & 2 Deck Framing & Lap Siding Installation Continued



Building B Unit 7 Front Fascia Installed



Building C4 Unit 35 Crawl Space Radon Vapor Barrier



Building E8 Unit 55 Deck Railing Installed



Building E8 Unit 56 Deck Railing Installed



Building E8 Unit 58 Deck Railing Installed



Daily Observation Report

Date of Report: Oct 14, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTER	NOR UNCHANES PHASE 7		R EPORT #: P2-282		
Address: Running Bear Road	IUR OPGRADES FIIASL Z		NLFONI #.1 2 202		
WEATHER					
TEMPERATURE	A.M		P.M		
Low Temperature: 29*	Snow		Windy		
High Temperature: 68*	X Mostly Sur	nny	Clear		
	Clear		Snow		
CONDITIONS	Other		X Mostly Sunny		
CREW ON SITE	-				
Plasterers Finish Carpenters	Plumbers	0	Radon System Installers		
Flooring Roofers 0	Concrete Coating Installer	0	Railing Installers		
Ceiling Sheet rockers/Tapers 0	Phase 1 punch list crew	12	Construction FA		
Landscapers Tile Setters 2	Painters	0	Superintendent		
Carpenter Others: 0	Helical Pier Installers	1	MCM		
TOTALS:	15				
Observations – 1) A: Units 1 & 2 Deck framing & back lap siding installation continued. 2) B: Units 3 & 4 Front snap batten siding installed. 3) E8: Units 55 - 58 Decking planks installed.					
TESTS/INSPECTIONS —					
UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —					





Building A Units 1 & 2 Deck Framing & Lap Siding Installed



Building B Units 3 & 4 Snap Batten Siding Installed



Building E8 Unit 56 Decking Installed



Building E8 Unit 57 Decking Installed