

Daily Observation Report

Date of Report: Oct 17, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2	REPORT #: P2-283

Address: Running Be	EAR ROAD				
WEATHER					
TEMPERATURE			A.M		P.M
Low Tempe	erature: 25*		Snow		Windy
High Temp	erature: 65*		X Mostly Sun	ny	Clear
			Clear		Snow
CONDITIONS			Other		X Mostly Sunny
CREW ON SITE					
Plasterers	Finish Carpenters		Plumbers	2	Satellite Installers
Flooring	Roofers	0	Concrete Coating Installer	2	Railing Installers
Ceiling	Sheet rockers/Tapers	0	Phase 1 punch list crew	7	Construction FA
Landscapers	Tile Setters	0	Painters	0	Superintendent
Carpenter	Others:	0	Helical Pier Installers	1	MCM
Totals: 12					
Observations – 1) A: Units 1 & 2 Deck framing continued. 2) B: Units 3 & 4 Front & back corrugated siding installation continued. Units 5 -7 satellite dish installed. 3) C4: Units 34 & 35 Satellite dish installed. 4) E5: Unit 42 Deck railing installed. TESTS/INSPECTIONS – UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –					





Building A Units 1 & 2 Deck Framing Completed



Building B Units 3 & 4 Front Corrugated Siding Installed



Building B Units 3 & 4 Back Corrugated Siding Installed



Building B Unit 5 Satellite Dish Installed



Building C4 Units 34 & 35 Satellite Dishes Installed



Building E5 Unit 42 Deck Railing Installed



Daily Observation Report

Date of Report: Oct 18, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & E.	XTEF	RIOR UPGRADES PHASE 2		Report # : P2-284
Address: Running Bear Road				
WEATHER				
TEMPERATURE		A.M		P.M
Low Temperature: 26*		Snow		Windy
High Temperature: 68*		X Mostly Sui	nny	Clear
		Clear		Snow
CONDITIONS		Other		X Mostly Sunny
CREW ON SITE				
Plasterers Finish Carpenters	_	Plumbers	2	Satellite Installers
Flooring Roofers	0	Concrete Coating Installer	2	Railing Installers
Ceiling Sheet rockers/Tapers	0	Phase 1 punch list crew	12	Construction FA
Landscapers Tile Setters	0	Painters	0	Superintendent
Carpenter Others:	0	Helical Pier Installers	1	MCM
Totals: 17				
Observations – 1) A: Units 1 & 2 Deck framing completed, fascia installed. Satellite dish installed. 2) B: Units 3 & 4 Satellite dish installed. Units 4 & 5 deck railing installed. 3) C5: Unit 40 Deck stairs installed. 4) C10: Unit 70 Deck stairs installed. 5) E5: Unit 42 Decking installed. 6) E9: Unit 64 Deck stairs installed. TESTS/INSPECTIONS –				
UNRESOLVED ISSUES/FACTORS CONTRIBUTING	TO	DELAY -		





Building A Unit 2 Deck Fascia Installed



Building A Units 1 & 2 Satellite Dish Installed



Building B Units 3 & 4 Satellite Dish Installed



Building B Unit 4 Deck Railing Installed



Building C10 Unit 70 Deck Stairs Installed



Building E5 Unit 42 Decking Installed





Building E9 Unit 64 Deck Stairs Installed



Daily Observation Report

Date of Report: Oct 19, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

REPORT #: P2-285

Address: Running Be	EAR ROAD			
WEATHER				
TEMPERATURE		A.M		P.M
Low Tempe	erature: 24*		Snow	Windy
High Temp	erature: 69*	X	Mostly Sunny	Clear
			Clear	Snow
CONDITIONS			Other	X Mostly Sunny
CREW ON SITE				
Plasterers	Finish Carpenters	Plumbers	3	Radon System Installers
Flooring	Roofers C	Concrete Coat	ing Installer 2	Railing Installers
Ceiling	Sheet rockers/Tapers 0	Phase 1 punch	list crew 12	Construction FA
Landscapers	Tile Setters 0	Painters	1	Superintendent
Carpenter	Others:	Helical Pier Ins	tallers 1	MCM
	Totals	: 19		
Observations – 1) A: Units 1 & 2 Crawlspace radon reduction system installed. 2) B: Units 4 & 5 Decking installed. 3) D: Unit 36 Deck railing installed. 4) E8: Units 55, 57 & 58 Deck stairs installed. 5) E9: Unit 61 Deck stairs installed. 6) E9: Unit 64 Deck stairs installed. 7) F1: Unit 16 Side fireplace vent blocking installed. TESTS/INSPECTIONS – UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –				





Building A Unit 2 Crawlspace Radon Remediation Damage Vapor Barrier Removed and Reinstalled



Building A Units 1 & 2 Radon Exhaust Installed



Building B Unit 4 Decking Installed



Building B Unit 5 Decking Installed





Building D Unit 36 Deck Railing Installed



Building E8 Unit 55 Deck Steps Installed



Building E8 Unit 57 Deck Steps Installed



Building E9 Unit 61 Deck Steps Installed



Building F1 Unit 16 Side Fireplace Vent Blocking Installed




Daily Observation Report

Date of Report: Oct 20, 2022 Prepared By: Jim Goveia

montanaconstrugint & gman.com

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTE	rior Upgrades Phase 2	Report # : P2-286	
Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 24*	Snow	Windy	
High Temperature: 71*	X Mostly Sunny	Clear	
	Clear	Snow	
CONDITIONS	Other	X Mostly Sunny	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers 1	. Garage Door Installer	
Flooring Roofers 0	Concrete Coating Installer 2	Railing Installers	
Ceiling Sheet rockers/Tapers 0	Phase 1 punch list crew 7	Construction FA	
Landscapers Tile Setters 0	Painters 1	Superintendent	
Carpenter Others: 0	Helical Pier Installers 1	MCM	
Totals:	12		
Observations – 1) B: Unit 4 Garage door opener installed. Units 3 - 7 Garage door weather stripping installed. Units 6 & 7 Deck stairs installed.2) D: Unit 36 & 37 Deck stairs installed. 3) E5: Units 42 & 44 Deck stairs installed. 4) E9: Unit 61 Deck railing installed. Observed wrong type railing installed instead of partial railing indicated. Tests/Inspections – Unresolved Issues/Factors Contributing to Delay –			





Building B Unit 3 Garage Weather Stripping Installed



Building B Unit 6 Deck Stairs Installed



Building B Unit 7 Deck Stairs Installed



Building D Unit 36 Deck Stairs Installed



Building D Unit 37 Deck Stairs Installed



Building E9 Unit 42 Deck Stairs Installed





Building E5 Unit 44 Deck Stairs Installed



Building E9 Unit 61 Deck Railing Installed



Daily Observation Report

Date of Report: Oct 21, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTE	rior Upgrades Phase 2	R EPORT #: P2-287	
Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 39*	Snow	Windy	
High Temperature: 62*	X Partly Cloud	dy 🗌 Clear	
	Clear	Snow	
CONDITIONS	Other	X Cloudy/Rain	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	0 Garage Door Installer	
Flooring Roofers 0	Concrete Coating Installer	0 Railing Installers	
Ceiling Sheet rockers/Tapers 0	Phase 1 punch list crew	4 Construction FA	
Landscapers Tile Setters 0	Painters	0 Superintendent	
Carpenter Others: 0	Helical Pier Installers	1 MCM	
Totals:	5		
Observations – 1) B: Unit 3 Deck stairs installed.			
TESTS/INSPECTIONS —			
UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO	DELAY –		





Building B Unit 3 Deck Stairs Installed