

## **Daily Observation Report**

Date of Report: Oct 24, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT &	FXTER	IOR UPGRADES PHASE 2		<b>R</b> EPORT #: P2-	288
Address: Running Bear Road	<b>L</b> XI LI	101.01.01.023777002		112. 511. 11. 12.	-00
WEATHER					
TEMPERATURE		A.M		P.M	
Low Temperature: 11*		Snow		Windy	
High Temperature: 34*		X Partly Clou	dy	Clear	
		Clear		Snow	
CONDITIONS		Other		X Mostly Sunny	
CREW ON SITE					
Plasterers Finish Carpenters		Plumbers	0	Garage Door Installer	
Flooring Roofers	0	Concrete Coating Installer	0	Railing Installers	
Ceiling Sheet rockers/Tapers	0	Phase 1 punch list crew	0	Construction FA	
Landscapers Tile Setters	0	Painters	1	Superintendent	
Carpenter Others:	0	Helical Pier Installers	1	MCM	
То	TALS:	2			
Observations – 1) No work performed today.					
TESTS/INSPECTIONS —					
UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —					



## **Daily Observation Report**

**REPORT #**: P2-289

Date of Report: Oct 25, 2022 Prepared By: Jim Goveia

**PROJECT:** BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 30*	Snow	Windy	
High Temperature: 47*	X Cloudy/Snow	Clear	
	Clear	Snow	
CONDITIONS	Other	X Mostly Sunny	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers 0	Garage Door Installer	
Flooring Roofers 0	Concrete Coating Installer 0	Railing Installers	
Ceiling Sheet rockers/Tapers 0	Phase 1 punch list crew 7	Construction FA	
Landscapers Tile Setters 0	Painters 1	Superintendent	
Carpenter Others: 0	Helical Pier Installers 1	MCM	
Totals:	9		
Observations – 1) Crew performed cleanup of waste materials and palletizing attic stock. 2) B: Units 3, 6 & 7 deck stairs completed. 3) C6: Unit 53 deck stairs completed.  TESTS/INSPECTIONS –  UNIDESOLVED ISSUES/EACTORS CONTRIBUTING TO DELAY –			
UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —			

1





Building E3 Unit 25 & 26 Front Parking Area Materials Removed



Building E4 Unit 28 & Building E2 Unit 23 Front Parking Area Materials Removed



**Building B Unit 3 Deck Stairs Installed** 



**Building B Unit 7 Deck Stairs Installed** 





**Building C6 Unit 53 Deck Stairs Installed** 



## **Daily Observation Report**

Date of Report: Oct 26, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

REPORT #: P2-290

Address: Running Be	ar Road			
WEATHER				
TEMPERATURE		A.M		P.M
Low Tempe	erature: 15*	Snow		Windy
High Temp	erature: 39*	X Cloudy		Clear
		Clear		Snow
CONDITIONS		Other		X Cloudy/Snow
CREW ON SITE				
Plasterers	Finish Carpenters	Plumbers	4	Radon System Installers
Flooring	Roofers 0	Concrete Coating Installer	0	Railing Installers
Ceiling	Sheet rockers/Tapers 0	Phase 1 punch list crew	7	Construction FA
Landscapers	Tile Setters 0	Painters	1	Superintendent
Carpenter	Others: 0	Helical Pier Installers	1	MCM
	Totals:	13		
Observations – 1) Deck joists prepared for installation. 2) B: Units 3 - 7 crawl space radon reduction system installed. Observed unit 3 side radon exhaust penetration was not as described in RFI, contractor to correct.  3) C7: Units 59 & 60 Deck plastic installed. 4) C8: Units 65 & 66 Deck plastic installed. 5) C9: Unit 67 Deck plastic installed.  TESTS/INSPECTIONS –  UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –				





Building B Unit 3 Side Radon Exhaust Penetration



**Building C7 Unit 60 Deck Plastic Installed** 



Building B Unit 7 Side Radon Exhaust Penetration



**Building C8 Unit 65 Deck Plastic Installed** 







**Building C9 Unit 67 Deck Plastic Installed** 



## **Daily Observation Report**

**REPORT #**: P2-291

Date of Report: Oct 27, 2022 Prepared By: Jim Goveia

**PROJECT:** BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

Address: Running Be	EAR ROAD			
WEATHER				
TEMPERATURE		A.M		P.M
Low Tempe	erature: 15*	Snow		Windy
High Temp	erature: 32*	X Mostly Clo	oudy	Clear
		Clear		Snow
CONDITIONS		Other		X Mostly Cloudy
CREW ON SITE				
Plasterers	Finish Carpenters	Plumbers	1	Garage Door Installers
Flooring	Roofers 0	Concrete Coating Installer	2	Railing Installers
Ceiling	Sheet rockers/Tapers 0	Phase 1 punch list crew	7	Construction FA
Landscapers	Tile Setters 0	Painters	1	Superintendent
Carpenter	Others: 0	Helical Pier Installers	1	MCM
	Totals:	12		
Observations – 1) A, B, C1, C2, E1, E2, E3, E4, F1 & F2: Garage door weather stripping installed. 2) A: Units 1 & 2 Siding corners installed. Unit 1 Deck stairs installed. 3) B: Units. 1 - 7 Siding corners installed. Units 3 & 7 Deck railing installed. 4) C6: Units 53 & 54 Siding corners installed. 5) E9: Unit 61 Decking installed.  TESTS/INSPECTIONS –  UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –				





Building E3 Unit 25 Garage Door Weather Stripping Installed



**Building A Unit 1 Deck Railing Installed** 



**Building B Unit 3 Deck Railing Installed** 



**Building B Unit 7 Deck Railing Installed** 



**Building C6 Unit 54 Front Corner Installed** 



#### **Daily Observation Report**

Date of Report: Oct 28, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

REPORT #: P2-292

Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 15*	Snow	Windy	
High Temperature: 36*	X Mostly Cloud	dy 🗌 Clear	
	Clear	Snow	
CONDITIONS	Other	X Mostly Cloudy	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	0 Garage Door Installers	
Flooring Roofers 0	Concrete Coating Installer	0 Railing Installers	
Ceiling Sheet rockers/Tapers 0	Phase 1 punch list crew	7 Construction FA	
Landscapers Tile Setters 0	Painters	0 Superintendent	
Carpenter Others: 0	Helical Pier Installers	1 MCM	
Totals:	8		
Observations – 1) E5: Unit 44 Decking installed. 2) E7: Units 49 - 52 Deck knee braces installation began. Observed incorrect lags being used & temporarily fastened.  TESTS/INSPECTIONS – UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –			





Building E7 Unit 52 Deck Knee Braces Installed



**Building E5 Unit 44 Decking Installed**