

Montana Construction Management PO Box 1508, Great Falls, MT 59401 (406) 799-9434 montanaconstmgmt@gmail.com

Daily Observation Report

Date of Report: Nov 7, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTER	IOR UPGRADES PHASE 2	R EPORT #: P2-298	
Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 23*	Snow	Windy	
High Temperature: 36*	X Cloudy/Snow	Clear	
	Clear	Snow	
CONDITIONS	Other	X Cloudy/Snow	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers 0	Garage Door Installers	
Flooring Roofers 0	Concrete Coating Installer 0	Railing Installers	
Ceiling Sheet rockers/Tapers 0	Phase 1 punch list crew 0	Construction FA	
Landscapers Tile Setters 0	Painters 1	Superintendent	
Carpenter Others: 0	Helical Pier Installers 1	MCM	
Totals:	2		
Observations – 1) No work performed today. 2) E2: Units 21 & 22 Front microwave vent blockout installed. 3) E3: Units 25 & 26 Front microwave vent blockout installed. 4) E4: Units 29 & 30 Front microwave vent blockout installed. 5) E5: Units 42 & 43 Front microwave vent blockout installed. 6) E6: Units 46 & 47 Front microwave vent blockout installed. 7) E7: Units 50 & 51 Front microwave vent blockout installed. 8) E8: Units 56 & 57 Front microwave vent blockout installed. 9) E9: Units 62 & 63 Front microwave vent blockout installed. TESTS/INSPECTIONS – UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –			





Building E2 Units 21 & 23 Microwave Vent Blockout



Building E3 Units 25 & 26 Microwave Vent Blockout



Building E4 Units 29 & 30 Microwave Vent Blockout



Building E5 Units 42 & 43 Microwave Vent Blockout



Building E6 Units 46 & 47 Microwave Vent Blockout



Building E7 Units 50 & 51 Microwave Vent Blockout





Building E8 Units 56 & 57 Microwave Vent Blockout



Montana Construction Management PO Box 1508, Great Falls, MT 59401 (406) 799-9434

Daily Observation Report

Date of Report: Nov 8, 2022 Prepared By: Jim Goveia

montanaconstmgmt@gmail.com

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTE	rior Upgrades Phase 2	Report # : P2-299
Address: Running Bear Road		
WEATHER		
TEMPERATURE	A.M	P.M
Low Temperature: 11*	Snow	Windy
High Temperature: 25*	X Cloudy/Snow	Clear
	Clear	Snow
CONDITIONS	Other	X Cloudy/Snow
CREW ON SITE		
Plasterers Finish Carpenters	Plumbers (Garage Door Installers
Flooring Roofers 0	Concrete Coating Installer C	Railing Installers
Ceiling Sheet rockers/Tapers 0	Phase 1 punch list crew 4	Construction FA
Landscapers Tile Setters 0	Painters 1	Superintendent
Carpenter Others: 0	Helical Pier Installers 1	MCM
Totals:	6	
Observations – 1) B: Unit 4 Observation front microwave blockout location will interfere with window and will not be installed. 2) C1: Unit 12 Side microwave/hood vent blockout installed. Observed new blockout for water meter not consistent with directed location. 3) C7: Unit 59 Side microwave/hood vent blockout installed. Observed right block bowed out in center proud of j channel. 4) E1: Units 9 & 10 Front microwave vent blockout installed. Observed wrong size blocking used in wrong locations. 5) E6: Units 45 - 48 garage door weather stripping installed.		
TESTS/INSPECTIONS —		
UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —		





Building C1 Units 12 Microwave Vent Blockout



Building C7 Units 59 Microwave Vent Blockout



Building E1 Units 9 & 10 Microwave Vent Blockout



Building E6 Unit 48 Garage Door Weather Stripping Installed



Montana Construction Management PO Box 1508, Great Falls, MT 59401 (406) 799-9434

Daily Observation Report

Date of Report: Nov 9, 2022 Prepared By: Jim Goveia

montanaconstmgmt@gmail.com

PROJECT: BIG HORN CO	DNDO SIDING REPLACEMENT & EXTER	RIOR UPGRADES PHASE 2		R EPORT #: P2-300
Address: Running Be	ear Road			
WEATHER				
TEMPERATURE		A.M		P.M
Low Tempe	erature: 5*	Snow		Windy
High Temp	erature: 28*	X Cloudy/Sno	ow	Clear
		Clear		Snow
CONDITIONS		Other		X Cloudy/Snow
CREW ON SITE				
Plasterers	Finish Carpenters	Plumbers	0	Garage Door Installers
Flooring	Roofers 0	Concrete Coating Installer	2	Railing Installers
Ceiling	Sheet rockers/Tapers 0	Phase 1 punch list crew	2	Construction FA
Landscapers	Tile Setters 0	Painters	2	Langlas
Carpenter	Others: 0	Helical Pier Installers	1	MCM
	Totals:	7		
Observations – 1) Interior punch list corrections continued. 2) Clean up continued. 3) C1: Unit 12 Side observed microwave hood blockout location consistent with RFI is 10" to far off corner. 4) C7: Unit 59 Side observed microwave hood blockout location consistent with RFI is 10" to far off corner. 5) E5: Unit 44 Deck railing completed. TESTS/INSPECTIONS – UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –				





Building E5 Unit 44 Deck & Stair Railing Installed



Montana Construction Management PO Box 1508, Great Falls, MT 59401 (406) 799-9434 montanaconstmgmt@gmail.com

Daily Observation Report

REPORT #: P2-301

Date of Report: Nov 10, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

Address: Running Bear Road				
WEATHER				
Temperature		A.M		P.M
Low Temperature: 5*		Snow		Windy
High Temperature: 28*		X Cloudy/Sno	W	Clear
		Clear		Snow
CONDITIONS		Other		X Cloudy/Snow
CREW ON SITE				
Plasterers Finish Carpenters	_	Plumbers	0	Garage Door Installers
Flooring Roofers	0	Concrete Coating Installer	0	Railing Installers
Ceiling Sheet rockers/Tapers	0	Phase 1 punch list crew	2	Construction FA
Landscapers Tile Setters	0	Painters	2	Langlas
Carpenter Others:	0	Helical Pier Installers	1	MCM
Total	.s:	5		
Observations – 1) E5: Unit 44 Decking reinstallation began.				
TESTS/INSPECTIONS -				
UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY —				

1





Building E5 Unit 44 Decking Reinstallation Began



Montana Construction Management PO Box 1508, Great Falls, MT 59401 (406) 799-9434 montanaconstmgmt@gmail.com

Daily Observation Report

Date of Report: Nov 11, 2022 Prepared By: Jim Goveia

PROJECT: BIG HORN CONDO SIDING REPLACEMENT & EXTERIOR UPGRADES PHASE 2

REPORT #: P2-302

Address: Running Bear Road			
WEATHER			
TEMPERATURE	A.M	P.M	
Low Temperature: 1*	Snow	Windy	
High Temperature: 20*	X Sunny	Clear	
	Clear	Snow	
CONDITIONS	Other	X Sunny	
CREW ON SITE			
Plasterers Finish Carpenters	Plumbers	2 Radon System Installers	
Flooring Roofers 0	Concrete Coating Installer	0 Railing Installers	
Ceiling Sheet rockers/Tapers 0	Phase 1 punch list crew	0 Construction FA	
Landscapers Tile Setters 0	Painters	0 Langlas	
Carpenter Others: 0	Helical Pier Installers	1 MCM	
Totals: 3			
Observations – 1) E2: Units 20 - 23 Radon exhaust pipes installed. 2) E4: Units 28 - 31 Radon exhaust pipes installed. 3) F1: Units 16 & 17 Radon exhaust pipes installed. 4) F2: Units 18 & 19 Radon exhaust pipes installed. TESTS/INSPECTIONS – UNRESOLVED ISSUES/FACTORS CONTRIBUTING TO DELAY –			

1





Building F2 Unit 19 Radon Exhaust Installed



Building E2 Units 21 & 22 Radon Exhaust Installed



Building E2 Unit 20 Radon Exhaust Installed



Building E2 Unit 23 Radon Exhaust Installed