

Printed: Mar 24, 2023 176 Running Iron Road, Gallatin Gateway, MT 59730 Phone: (406)993-2533

Mar 23, 2023

Job:HPM - SP Condos Unit 23-27Added By:Garret IversonLog Notes:Image: Site CheckTasks performed: Site CheckImage: Site Check

The team has almost completed the all rafters on the Southern side of building and started installing sleepers on northern side. They were also made aware of the roof extension from the upper roof to the roof below to allow for better airflow per the stamped plan set.

They started to tear off the lower roofs and dry them in.

The team was made aware that they need to be tied off and aware of their ropes while maneuvering on the roof. Otherwise all team members had high vis and harness on as well as ladders being tied off and cones and caution tape up.

It was communicated that the team needs to cover the roof with provided poly to prevent snow from covering the framing.

Future Tasks: Continue framing and start sheathing the roof.

Weather Conditions:

Mostly Sunny

45° F 13° F Wind: 10 mph Humidity: 87% Total Precip: 0" Thu, Mar 23, 2023, 4:14 PM

Custom Fields
CMS Employees: Garret Iverson, Garrett Damm
Subs Onsite: CE Hernandez Construction
Tool Box Talk:
Delivery:
Added Work:
Site issues: N/A
Tools & Equipment: N/A
Materials: N/A

Attachments:

Daily Log Print

