

Printed: May 5, 2023 176 Running Iron Road, Gallatin Gateway, MT 59730 Phone: (406)993-2533

May 4, 2023

Job:HPM - SP Condos Unit 23-27Added By:Garrett DammLog Notes:IterationTasks performed: Punch List

- 1. Fix and seal the chimney curbs
- 2. Replace valley shingles
- 3. Replace damaged shingles and seal exposed fasteners
- 4. Cut the cricket sheathing to not have an abrupt edge
- 5. Fasten and seal the end wall metal
- 6. Fix and seal the bird box flashing
- 7. Add pipe cap and storm collar on pipe

Future Tasks:

Tags:

Punch, QAQC WALK

Weather Conditions:

Partly Cloudy with Isolated Storms



Wind: 22 mph Humidity: 69% Total Precip: 0.07"

| Thu, Ma | y 4, | 2023, | 7:46 | AM |
|---------|------|-------|------|----|
|---------|------|-------|------|----|

| Custom Fields |
|--|
| CMS Employees: Garrett Damm |
| Subs Onsite: CE Hernandez Construction |
| Tool Box Talk: |
| Delivery: |
| Added Work: |
| Site issues: N/A |
| Tools & Equipment: N/A |
| Materials: N/A |

Attachments:

Daily Log Print

