

Printed: Jun 16, 2023 176 Running Iron Road, Gallatin Gateway, MT 59730 Phone: (406)993-2533

Daily Log Print

Jun 16, 2023

Job: HPM - SP Condos Unit 38-42

Garrett Damm

Title: Added By:

Log Notes:

Tasks performed: Punch Walk

- 1. Replace siding
- 2. Install new flashing
- 3. Install flashing
- 4. Finish installing flashing
- 5. Add flashing in bird box to close out the shingles
- 6. Seal fasteners on chimneys
- 7. Add sidewall flashing under the fascia
- 8. Repair fascia where it was cut
- 9. Fix shingles
- 10. Seal exposed fasteners

Future Tasks:

Weather Conditions:

Partly Cloudy with Isolated Storms



Wind: 8 mph Humidity: 99% Total Precip: 0"

Custom Fields

CMS Employees: Garret Iverson, Garrett Damm	
Subs Onsite: CE Hernandez Construction	
Tool Box Talk:	
Delivery:	
Added Work:	
Site issues: N/A	
Tools & Equipment: N/A	
Materials: N/A	

Fri, Jun 16, 2023, 12:56 PM

Attachments:

Daily Log Print

